NM OIL CONSERVATION

ARTESIA DISTRICT

<u>District I</u>
1625 N. French Dr., Hobbs, NM 88240
<u>District II</u>
811 S. First St., Artesia, NM 88210
<u>District III</u>
1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

APR 2 8 2015

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 SPECET ED appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action OPERATOR Initial Report Final Report Name of Company MATADOR PRODUCTION COMPAN Contact AVA MONROE 5400 LBJ FREEWAY, STE. 1500, DALLAS, TX 75240 Telephone No. 972-371-5218 Facility Name Tiger 14-24S-28E RB #224H Facility Type TB flare point Surface Owner Mineral Owner API No. 30-015-42873 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County Ρ 505 SOUTH 254 **EAST EDDY** 14 **24S** 28E Latitude 32.2117786 Longitude -104.0496028 NATURE OF RELEASE Type of Release FLARED GAS Volume of Release BELOW Volume Recovered N/A TB FLARE POINT Source of Release Date and Hour of Occurrence Date and Hour of Discovery Was Immediate Notice Given? If YES, To Whom? Yes No Not Required By Whom? Date and Hour Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes 🕅 No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* NEW WELL: FLARING BEGAN DUE TO PLANT/PL SHUT IN ON DAY WELL INTIALLY CONNECTED. WELL AVERAGED 519 MCFD FLARING THROUGH 4/22/2015. APPEARS TO BE RESOLVED AS OF 4/22/15. 13501 MCF TTL VOL FLARED APRIL. Describe Area Affected and Cleanup Action Taken.* I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: MIMON Approved by Environmental Specialist: Ava Monroe Printed Name: Sr. Engineering Technician Title: **Expiration Date:** E-mail Address; amonroe@matadorresources.com Conditions of Approval: Attached 4/28/15 Phone: 972-371-5218

* Attach Additional Sheets If Necessary

2RP-2970