

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 30 2011

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form
NMOCD ARTESIA

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company – Devon Energy	Contact – Roy White, Foreman
Address – 6488 Seven Rivers Hwy – PO Box 250	Telephone No. – 575-513-1741
Facility Name – Ore Ida 14 Federal #10	Facility Type

Surface Owner	Mineral Owner	Lease No. API # 30-015-29290 2RP-798
---------------	---------------	---

LOCATION OF RELEASE

Unit Letter I	Section 14	Township 24S	Range 29E	Feet from the 1780'	North/South Line South	Feet from the 860'	East/West Line East	County Eddy
-------------------------	----------------------	------------------------	---------------------	-------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------

Latitude 32.21516 Longitude -103.94927

NATURE OF RELEASE

Type of Release – Produced Water	Volume of Release 100 bbls	Volume Recovered -0- bbls
Source of Release – Above ground poly line was run over	Date and Hour of Occurrence 5/11/11 – 10:00 pm	Date and Hour of Discovery 5/11/11 – 10:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos	
By Whom? – Roy White, Foreman	Date and Hour 5/12/11 – 9:10 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A truck had ran over an above ground poly line causing damage to the line releasing 100 bbls of produced water with 0 bbls recovered.

Describe Area Affected and Cleanup Action Taken.*

Talon/LPE excavated the saturated soil from the impacted lease road to a depth of 1-2 feet deep and approximately 1,200-feet in length. The excavated material was transported to a NMOCD approved Solid Waste disposal facility. Talon/LPE backfilled the area with new material transported from a local borrow pit. The backfill material was contoured to match existing lease road.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: David Adkins, TALON/LPE	Approved by District Supervisor: 	
Title: Agent/Devon Energy	Approval Date: 5/24/15	Expiration Date: N/A
E-mail Address: dadkins@talonlpe.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 11/14/11 Phone: 575-746-8768		

* Attach Additional Sheets If Necessary

2RP-798