

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company OXY USA	Contact Kelton Beard
Address 1502 W. Commerce	Telephone No. (O) 575-628-4121 C) 575-390-1903
Facility Name Jones Canyon 4-6	Facility Type Well with Battery

Surface Owner BLM	Mineral Owner BLM	Lease No. 3001530948
-------------------	-------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	4	22S	24E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 20	Volume Recovered 4
Source of Release Thrust Chamber on SWD pump	Date and Hour of Occurrence	Date and Hour of Discovery 7-19-09
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (left message)	
By Whom? Rick Kerby (HES-Oxy)	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The thrust chamber on the SWD pump was leaking. Vac-truck was called to pick up remaining fluid

Describe Area Affected and Cleanup Action Taken.*

Area affected was on location. Delineation occurred and all levels were below RAL's except TP6. At TP6, 1 foot of material was excavated and hauled to an approved disposal (Lea Land). Clean like material was brought in for backfill. All other material was left in place.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kelton Beard	Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 4/24/15	Expiration Date: N/A
E-mail Address: kelton_beard@oxy.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 4-6-10		

* Attach Additional Sheets If Necessary

2RIP-688