

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

RTM 1303140115 OPERATOR Initial Report Final Report

Name of Company XTO Energy Inc. 5380	Contact Velma Gallardo, Production Analyst
Address 200 North Loraine Ste 800, Midland, TX 79701	Telephone No. 432-620-4315
Facility Name Remuda Basin	Facility Type Bulk Petroleum Storage facility/Battery
RESPONSIBLE PARTY: TPG Transport LLC 3819 Towne Crossing Blvd Suite 100, Mesquite, TX 75150	

Surface Owner	Mineral Owner	Lease No. 080423
---------------	---------------	-------------------------

LOCATION OF RELEASE *API # 30-015-28400*

Unit Letter	Section 19	Township 23S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude **32.2908N**

Longitude **103.9217W**

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 53 bbls	Volume Recovered 46 bbls
Source of Release Cargo trailer overflow.	Date and Hour of Occurrence: Monday Aug 30, 2010 09:00 CST	Date and Hour of Discovery- reported Monday Aug 30, 2010 09:00 CST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? XTO Energy Inc. - Jerry Parker, Production Foreman	
By Whom? James Brown, Team Leader, TPG Transport LLC	Date and Hour 09:00 CST Monday August 30, 2010	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* **no impact to waterways.**

Describe Cause of Problem and Remedial Action Taken.*

Driver overflowed cargo trailer resulting in a 53 bbl crude oil release. Release was contained within the facility berm.

Incident Investigation pending.

Describe Area Affected and Cleanup Action Taken.* Vac truck removed standing oil. Environmental remediation by Talon LPE (contracted by TPG Transport LLC), locates completed Sept 1, soil sampling Thursday Sept 2, based on lab analytical remedial action will be either on site blending and replacement or off-site disposal and backfill with clean material.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Celeste Kaban
Signature:

Printed Name: **Celeste Kaban**

Signed By *Mike Brown*

Title: **HSSE & Environmental Compliance**
TPG Transport LLC

Approval Date: **JAN 31 2013**

Expiration Date:

E-mail Address: **celestek@taylorgasliquids.com**

Conditions of Approval:

Attached

Date: **September 2, 2010** Phone: **214-461 5563 (office)**
903-466-2867 (mobile)

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. **SUBMIT REMEDIATION**

PROPOSAL NO LATER THAN:

March 1, 2013

2RP-1534