

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Chevron Delaware Basin	Contact	Bradley Blevins
Address	PO Box 190, Hobbs, NM 88241	Telephone No.	(575) 391-1462
Facility Name	Benson Shugart WFU #2 CTB	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API #	
---------------	-----	---------------	--	-------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	26	18S	30E	2310	South	330	East	Eddy County, NM

Latitude N 32.71738° Longitude W 103.93519°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	59 bbls	Volume Recovered	51 bbls
Source of Release	Tank overflow	Date and Hour of Occurrence	07/29/2013 @ 10:00 am	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- NMOCD; James Amos- BLM		
By Whom?	Bradley Blevins	Date and Hour	07/29/2013 @ 3:22 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

OCT 25 2013

Describe Cause of Problem and Remedial Action Taken.*

Failure to get a load from the tank caused an overflow and 59 bbls of produced water leaked onto the ground. 51 bbls of produced water were recovered via vacuum truck.




NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.*

Failure to get a load from the tank caused an overflow and 59 bbls of produced water leaked onto the ground. 51 bbls of produced water were recovered via vacuum truck. Remediation was completed in accordance with the remediation plan verbally approved by Mike Bratcher of NMOCD and approved by Mike Burton of the BLM via email on 09/20/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 	
Printed Name: Bradley Blevins	Approval Date: 5/11/15	Expiration Date: N/A
Title: HE Specialist	Conditions of Approval: 	Attached <input type="checkbox"/>
E-mail Address: Bradley.blevins@chk.com		
Date: 10/23/2013	Phone: (575) 391-1462	

* Attach Additional Sheets If Necessary

24P-1772