

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

NAB1514-250277

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Mewbourne Oil Company <i>14744</i>	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Zircon Compressor Facility / State HL #1	Facility Type: Oil producing Well

Surface Owner: State	Mineral Owner: State	API No. 30-015-23065
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	I	19S	29E	660'	South	1980'	West	Eddy

Latitude 32.68388 Longitude -104.03062

NATURE OF RELEASE

Type of Release: Oil/produced water	Volume of Release: estimated 20 bbls	Volume Recovered: N/A
Source of Release: Compressor catch tank	Date and Hour of Occurrence: 5-19-15	Date and Hour of Discovery: 5-19-15 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD	
By Whom? Zack Thomas	Date and Hour 5-19-15 2:18 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Cause of the leak- Dump failure on well separator causing fluid to go down gas line to Zircon Compressor Facility causing catch tank to be over filled. Dump on separator was fixed to stop the release.		
Describe Area Affected and Cleanup Action Taken.* Leaked fluid affected the pad surface around the catch tank and also ran off location to the west an estimated 200 yards in to the pasture.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>Z. Thomas</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Zack Thomas	Approval Date: <i>5/22/15</i>	Expiration Date: <i>N/A</i>
Title: Environmental Rep.	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
E-mail Address: zthomas@mewbourne.com	Attached <input type="checkbox"/>	
Date: 5-20-15 Phone: 575-602-2188	SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: 6/22/15

2RP-3009

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Zack Thomas <zthomas@mewbourne.com>
Sent: Wednesday, May 20, 2015 12:04 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: Zircon Compressor Facility/ State HL #1
Attachments: IMG_0035.JPG; IMG_0046.JPG; IMG_0041.JPG; C141- Zircon Compressor Facility (5-19-15) MOC signed Initial.pdf



Zack Thomas
Environmental Rep.
Mewbourne Oil Company
PO Box 5270
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252
(575) 602-2188
Email: zthomas@mewbourne.com