

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

**AB1515927960**

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Devon Energy Production		Contact Randy Gladden	
Address 6488 Seven Rivers Hwy Artesia, NM 88220		Telephone No. 575.513.9463	
Facility Name Aldabra 25 Fed 6 Battery		Facility Type Oil	
Surface Owner Federal		Mineral Owner Federal	API No. 30-015-38602

LOCATION OF RELEASE

Unit Letter P	Section 25	Township 23S	Range 31E	Feet from the 200	North/South Line FSL	Feet from the 1050	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32.1607 Longitude: 103.4335

NATURE OF RELEASE

Type of Release Spill .25 BBL Oil & 1.75 BBL Produced Water	Volume of Release .25 Oil BBL & 1.75 BBL Produced Water	Volume Recovered .25 BBL & 1 BBL Produced Water
Source of Release 3 Phase Separator	Date and Hour of Occurrence 6/3/15 12:00PM	Date and Hour of Discovery 6/3/15 12:00PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM	
By Whom? Randy Gladden	Date and Hour 6/5/15 1:45 PM	NM OIL CONSERVATION ARTESIA DISTRICT JUN 5 2015
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.\*

RECEIVED

Describe Cause of Problem and Remedial Action Taken.\*

At the Aldabra 25-6 & 7 battery at 12:00 pm the 3 phase separator was blowing out of the gasket on water dump manway. Lease operator saw the gasket blowing a mist so he went to the battery and noticed it was the Aldabra 25-3 separator. He shut the well down and shut it in, he then went to battery and shut it at the header.

Describe Area Affected and Cleanup Action Taken.\*

It was mostly in containment an over spray, went onto pasture. .25 bbl of oil and 1.75 bbl produced water was release and .25 BBL of oil and 1 BBL of produced water was recovered. The 15 X 20 area will be pressure sprayed with soap and water also evaluated by environmental group. Vendor called to replace gasket.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Jeanette Barron		OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support		Approval Date: 6/8/15	Expiration Date: N/A
E-mail Address: Jeanette.barron@dmv.com		Conditions of Approval:	
Date: Phone: 575.748.1813		Remediation per O.C.D. Rules & Guidelines checked <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 7/1/15	

\* Attach Additional Sheets If Necessary

2RP-3036

**Patterson, Heather, EMNRD**

---

**From:** Barron, Jeanette <Jeanette.Barron@dvn.com>  
**Sent:** Friday, June 05, 2015 3:03 PM  
**To:** jamos@blm.gov; shughes@blm.gov; jrobertson@blm.gov; Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Cc:** Gladden, Randy; Aguilar, Leonard; Suniga, Dan; Galindo, Bert  
**Subject:** Aldabra 25 6 & 7 Battery  
**Attachments:** C-141 Aldabra 25 6 & 7 Battert spill 6.3.15.doc; Aldabra 25 6 & 7 Pic 3 of 5.jpg; Aldabra 25 6 & 7 Pic 4 of 5.jpg; Aldabra 25 6 & 7 Pic 5 of 5.jpg; Aldabra 25 6 & 7 Pic 1 of 5.jpg; Aldabra 25 6 & 7 Pic 2 of 5.jpg

*Please see attached*

*Thanks,*

**Jeanette Barron**

*Field Admin Support-Production*

**Devon Energy Corporation**

*P.O. Box 250*

*Artesia, NM 88211*

*575 748 1813 Direct*

*jeanette.barron@dvn.com*

**devon**

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.