NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

JUN 1.0 2015

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit Leftop to appropriate District Office in accordance with 19,15,29 NMAC.

f4B1437.841543 **Release Notification and Corrective Action** NAB1516226673 **OPERATOR** Initial Report Name of Company Enterprise Field Services LLC Contact Dina Ferguson PO Box 4324, Houston, TX 77210 Telephone No. 210-528-3824 Pipeline ROW, 30137 Gathering Lateral Facility Name Facility Type: Gas Gathering Pipeline State of New Mexico Mineral Owner NA - Pipeline Surface Owner Lease No. NA LOCATION OF RELEASE Unit Letter Township Feet from the North/South Line Feet from the East/West Line County Section Range 198 28E 70 South 388 West Eddy 0 Latitude: N 32.653899 Longitude: W-104.129186 NATURE OF RELEASE Type of Release Natural Gas, Pipeline Liquids Volume of Release: 1.574 MCF. Volume Recovered: N/A 3 BBL Liquids Source of Release Pipeline Leak. Date and Hour of Discovery Date and Hour of Occurrence 06/08/2015 @ 8:50 MDT 06/08/2015 @ 9:38 MDT Was Immediate Notice Given? If YES, To Whom? Mike Bratcher - NMOCD District 2 By Whom? Osman De Leon Date and Hour 06/08/2015 @ 9:38 MDT Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ⊠ No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Pipeline leak was detected by an Enterprise Inspector. Pipeline segment was clamped and blown down, and leaking portion will be repaired following standard One-Call. Describe Area Affected and Cleanup Action Taken.* Liquid spill occurred within pipeline ROW. Clean-up activities will be carried out in accordance with Enterprise's General release Notification, Response and Remediation Plan according as defined in the housekeeping standards. Enterprise will maintain records of sampling results and disposal documentation, and will make available to NMOCD upon request. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Signed By Approved by District Supervisor: Printed Nan Jon E. Fields Title: Approval Date: Expiration Date: Director, Field Environmental E-mail Address: jefields@eprod.com Conditions of Approval Attached 6-8-2015 Phone: 713-381-6684

* Attach Additional Sheets If Necessary

2RP-3044

Bratcher, Mike, EMNRD

From:

Nolan, Shiver <SNolan@eprod.com>

Sent:

Wednesday, June 10, 2015 8:36 AM

To:

Bratcher, Mike, EMNRD

Subject:

Eddy County C-141 30137 Gathering Lateral

Attachments:

Eddy County C-141 30137 Gathering Lateral (Final) June 2015.pdf

Attached for your handling and review is the subject report. Please contact Dina Ferguson should you need additional information.

Shiver Nolan

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.