

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1516952580

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>th</sup> Street	Telephone No. 575-748-1471	
Facility Name Kent BSK #1H	Facility Type Battery	

Surface Owner Fee	Mineral Owner Fee	API No. 30-015-40161
----------------------	----------------------	-------------------------

LOCATION OF RELEASE

Unit Letter P	Section 20	Township 18S	Range 26E	Feet from the 400	North/South Line South	Feet from the 330	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.72711 Longitude 104.39612

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 15 B/PW	Volume Recovered 15 B/PW
Source of Release Production Tank	Date and Hour of Occurrence 5/30/2015; AM	Date and Hour of Discovery 5/30/2015; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION  
ARTESIA DISTRICT  
JUN 17 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The production tank overflowed, causing the release. Vacuum truck(s) were called.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 130' X 20' within the lined/bermed battery. The valves were closed and all of the produced water was recovered (100%). Depth to Ground Water: 50-90' (approximately 90', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on all released produced water recovered and the battery being lined and bermed, Yates Petroleum Corporation requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: NM Environmental Regulatory Supervisor	Approval Date: 6/18/15	Expiration Date: N/A
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: 2RP- FINAL	Attached <input type="checkbox"/>
Date: June 17, 2015	Phone: 575-748-4217	

\* Attach Additional Sheets If Necessary

2RP-3054

**Patterson, Heather, EMNRD**

---

**From:** Tanna Adams <TCAAdams@yatespetroleum.com>  
**Sent:** Wednesday, June 17, 2015 3:32 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** Bob Asher; Amber Cannon; Chase Settle; Katie Parker; Veronica Alvarado  
**Subject:** Kent BSK #1H C141  
**Attachments:** Kent BSK #1H\_C141\_InitialFinal\_053015.pdf

Good afternoon,

Please find attached the signed C141 Initial/Final for the below listed location:

**Kent BSK #1H**  
**30-015-40161**  
**Section 20, T18S-R26E**  
**400 FSL & 330 FEL**  
**Eddy County, New Mexico**

Thank you,

*Tanna Adams*  
Yates Petroleum Corporation  
Environmental Tech  
Environmental Department  
[TCAAdams@yatespetroleum.com](mailto:TCAAdams@yatespetroleum.com)

---

**This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.**

---