



Michelle Mullins
Environmental Coordinator

June 9, 2014

Oil Conservation Division
District 2 – Artesia
811 S. First St.
Artesia, NM 88210

NM OIL CONSERVATION
ARTESIA DISTRICT
JUN 09 2014

Re: Honey Graham 29 State Com #6H
30-015-38488
Sec. 29 T26S-R28E
Eddy County, NM

RECEIVED

Mr. Bratcher,

COG would like to submit the enclosed document for closure of the Honey Graham 29 State Com #6H release that was reported on the C-141 Initial submitted February 3, 2014.

All work has been completed in accordance with the approved work plan submitted on March 27, 2014. Remediation of the site is complete with all impacted material hauled to an approved NMOCD facility for disposal and backfill as described in the work plan.

A signed C-141 Final is enclosed for your consideration. Please feel free to contact me with any further questions or concerns at (432) 934-1052.

Sincerely,

A handwritten signature in cursive script, appearing to read "Michelle Mullins".

Michelle Mullins

Enclosure: C-141 (initial)
C-141 (final)

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Honey Graham 29 State Com #006H	Facility Type	Flowline
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-38488

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	29	26S	28E					Eddy

Latitude 32.06168

Longitude 104.09991

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced water	12bbls	10bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Polyline Y connection	01-22-2014	01-22-2014 11:00am
Was Immediate Notice Given?	If YES, To Whom?	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required		
By Whom?	Date and Hour	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT

Describe Cause of Problem and Remedial Action Taken.*

JUN 09 2014

The weld on the Y failed. Cut out the bad connection and welded the polyline.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*

Initially 12bbls of produced water were released. We were able to recover 10bbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Robert Grubbs Jr.

Approved by District Supervisor:

Title: Senior Environmental Coordinator

Approval Date:

Expiration Date:

E-mail Address: rgrubbs@concho.com

Conditions of Approval:

Attached ☐

Date: 02-03 -2014 Phone: 432-661-6601

* Attach Additional Sheets If Necessary

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Honey Graham 29 State Com #006H	Facility Type	Flowline
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-38488

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	29	26S	28E					Eddy

Latitude 32.06168 Longitude 104.09991

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced water	12bbls	10bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Polyline Y connection	01-22-2014	01-22-2014 11:00am
Was Immediate Notice Given?	If YES, To Whom?	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required		
By Whom?	Date and Hour	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 09 2014

RECEIVED

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The weld on the Y failed. Cut out the bad connection and welded the polyline.

Describe Area Affected and Cleanup Action Taken.*

Initially 12bbls of produced water were released. We were able to recover 10bbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Michelle Mullins	Approved by District Supervisor:		
Title: Environmental Coordinator	Approval Date:	Expiration Date:	
E-mail Address: mmullins@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 06-06-2014	Phone: 432-934-1052		

* Attach Additional Sheets If Necessary