State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

1

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

220 S. St. Fran	eis Dr., Santa	a Fe, NM 87505	5	Sa Sa	inta F	e, NM 875	505					
			Rele	ease Notific	catio	n and Co	orrective A	ction				
NABI	5197	51981	·			OPERA	ΓOR		🖾 1nitiz	al Report	Final Repo	
Name of Company Oxy Permian Ltd. 141946							Chancey Summe					
							No. (432) 685	5-5824				
Facility Nar	ne FNR	26 Federal	#1 CTB			Facility Typ	be Battery					
Surface Owner BLM Mineral Owner									API No	. 30-15-3	0412	
	<u> </u>			TOCA		N OF RE	FASE		, I , —			
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/W	Vest Line	County		
·										•		
D	31	235	31E			······				Eddy Cou	nty, NM	
			l	Latitude <u>N 32.2</u>	<u>6522°</u>	Longitu	de <u>W 103.8231</u>	<u>5°</u>				
				ΝΔΤ	TIRE	OFREL	FASE					
Type of Rele	ase Oil a	nd Produced v	vater		ONE		OF RELEASE Volume of Release 10 bbls oil, Volume Recovered 0 bbls					
							70 bbls produced water					
Source of Re	lease Stre	ess/fatigue of	a 3" water	transfer line			Date and Hour of Occurrence Date and Hour of Discovery				scovery	
Was Immedia	ata Notico (Sivon?		<u> </u>	<u> </u>	05/20/201:	/20/2015 YES, To Whom?					
** as miniculi			Yes 🛛	No 🗌 Not Re	equired							
By Whom?							Date and Hour					
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.					
🗌 Yes 🛛 No						ARTESIA DISTRICT						
Describe Cau	use of Probl	em and Rome	dial Actio	n Taken.*	,						JUL 1 4 2015 RECEIVED	
Stress/fatigue no fluids wer			ne causéd	10 bbls oil and 70	bbls of	f produced wa	ter to leak onto th	e ground	I. The line	was repaire	ed or replaced and	
Describe Are	a Affected	and Cleanup /	Action Tal	(en.*		<u> </u>						
	area is appr	-		off of location. Re	emediat	tion will be co	mpleted in accord	lance wi	th a remed	iation plan a	approved by	
regulations al public health should their o	ll operators or the envir operations h nment. In a	are required to ronment. The ave failed to a ddition, NMC	o report ar acceptanc idequately QD accep	e is true and comp nd/or file certain r ce of a C-141 report investigate and r trance of a C-141	elease r ort.by th emediat	notifications a ne NMOCD m te contaminati	nd perform correct arked as "Final R on that pose a thr	ctive acti leport" d reat to gr	ons for rele oes not reli ound water	eases which eve the ope , surface wa	may endanger rator of liability ater, human health	
		\mathcal{F}	\bot		T		OIL CON	SERV	ATION	DIVISIO	DN-7	
Signature:	L	\geq							.//	/ /		
A							Approved by Environmental Specialist:					
Printed Name	: Chance	y Summers							_1/	$\underline{\vee \nu}$	\sim	
Title: HES	Lead					Approval Da	te: 11615)	Expiration 1	Date: N	H	
		(~								, <u></u>	
E-mail Addro	ss: <u>Chan</u>	eev_Summers	<u>steboxy.com</u>	<u>]]</u>		Conditions of	f Approval: per O.C.D. F	uloe ^g	. Guideli			
Date: 7-	13-15	5	Phone:	(432) 685-58	24		HEDIATION F	NBUDU	SAL NC		—	
Attach Addit	. / /			(152) 005-50		TER THAN)			
					مى مەر			1-0		14	2p.312D	
										<i>v</i> 1	•	

Patterson, Heather, EMNRD

From: Sent: To: Cc:	Kathy Purvis <kathy@bbcinternational.com> Tuesday, July 14, 2015 12:24 PM Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jeffery Roberston; jamos@blm.gov C J Summers; Susan Miller; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com</kathy@bbcinternational.com>
Subject: Attachments:	kswinney@bbcinternational.com; jgilkey@bbcinternational.com Initial C-141, FNR 26 Federal #1 CTB, 5-20-15 Initial C-141, FNR 26 Federal #1 CTB.pdf

Attached is the initial C-141 for a leak that occurred at the FNR 26 Federal #1 CTB on 05/20/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240 Phone: (575) 397-6388 Fax: (575) 397-0397 Email: <u>kathy@bbcinternational.com</u>