

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 14 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1520234531



OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report		
Name of Company Yates Petroleum Corporation <i>25575</i>	Contact Robert Asher	
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Humidor BML State Com #5H	Facility Type Battery	
Surface Owner State	Mineral Owner State	API No. 30-015-42755

LOCATION OF RELEASE

Unit Letter I	Section 26	Township 24S	Range 27E	Feet from the 2365	North/South Line South	Feet from the 575	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.20188 Longitude 104.1544

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 15 B/PW	Volume Recovered 6 B/PW
Source of Release Poly Line	Date and Hour of Occurrence 7/1/2015; AM	Date and Hour of Discovery 7/1/2015; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The poly line failed, causing the release. Vacuum truck(s) and roustabout crews were called.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 12' X 10'. The wells were shut in, vacuum trucks were called to recover the spill, and a roustabout crew was called to repair the poly line. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (approximately 50', Section 26, T24S-R27E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Signed By  Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>7/21/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: <input type="checkbox"/> Remediation per O.C.D. Rules & Guidelines	
Date: July 14, 2015	SUBMIT REMEDIATION PROPOSAL NO	
Phone: 575-748-4217	LATER THAN: <u>7/22/15</u>	

* Attach Additional Sheets If Necessary

2 RP-3135

Bratcher, Mike, EMNRD

From: Tanna Adams <TCAAdams@yatespetroleum.com>
Sent: Tuesday, July 14, 2015 4:25 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Bob Asher; Amber Cannon; Chase Settle; Katie Parker; Veronica Alvarado
Subject: Humidor BML State Com #5H
Attachments: Humidor BML State Com #5H_C141_Initial_070115.pdf

Good afternoon,

Please find attached the C141 Initial for the below listed location:

**Humidor BML State Com #5H
30-015-42755
Section 26, T24S-R27E
2365 FSL & 575 FEL
Eddy County, New Mexico**

Thank you,

Tanna Adams

Yates Petroleum Corporation

Environmental Technician

Environmental Department

Office: (575) 748-4184

TCAAdams@yatespetroleum.com



This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
