

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1520434154

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Devon Energy Production Co LP (6137)	Contact: Brian Kuh	
Address: PO Box 250 Artesia, NM 88211	Telephone No. 575- 616-1540	
Facility Name: Hackberry 16 SWD 1	Facility Type: Off well location in pasture	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-41783

LOCATION OF RELEASE

Unit Letter M	Section 16	Township 19S	Range 31E	Feet from the 330	North/South Line South	Feet from the 280	East/West Line West	County Eddy
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------

Latitude: **32.653269** Longitude: **103.889203**

NATURE OF RELEASE

Type of Release: Treated Water	Volume of Release: 75-100 bbls	Volume Recovered: 0 bbl
Source of Release: Ruptured Water Transfer Lines	Date and Hour of Occurrence 7/15/15, 3:50 PM	Date and Hour of Discovery 7/15/15, 4:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher	BLM-Jeff Robertson
By Whom? Brian Kuh, Devon Foreman	Date and Hour: 7/16/15, 6:30 AM	7/16/15, 6:25 AM
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 21 2015

Describe Cause of Problem and Remedial Action Taken.*

Rock Water Energy was in the process of transferring treated water from the Hackberry 16 SWD 1 to the Strawberry 7 Fed Com 11H frac location when the lay flat transfer line shredded apart near the coupling causing approximately 75-100 barrels of treated water to release in the pasture. The area was approximately 22,000 square feet, 524 feet x 151 feet laying along the 2-track and flowing North of the 2-track.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck was not able to reach the spill location due to the unsafe and impassable terrain. Talon was commissioned to inspect the spill area and submit a remediation plan for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: 7/23/15	Expiration Date: NIA
E-mail Address: Denise.Menoud@dvn.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: 7/20/2015 Phone: 575-746-5544	SUBMIT REMEDIATION PROPOSAL NO	

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN:

* Attach Additional Sheets If Necessary

2RP-3145

Patterson, Heather, EMNRD

From: Menoud, Denise <Denise.Menoud@dvn.com>
Sent: Tuesday, July 21, 2015 9:38 AM
To: 'jamos@blm.gov'; Patterson, Heather, EMNRD
Cc: Kuh, Brian; Fulks, Brett; Harris, Jacqui; Menoud, Denise
Subject: C-141 - Spill Hackberry 16 SWD 1 area 7/15/15
Attachments: map of 75 BPW spill 7_15_15.pdf; FullSizeRender7.jpg; FullSizeRender8.jpg; FullSizeRender9.jpg; FullSizeRender10.jpg; FullSizeRender11.jpg; FullSizeRender12.jpg; FullSizeRender14.jpg; FullSizeRender15.jpg; FullSizeRender 1.jpg; FullSizeRender 2.jpg; FullSizeRender 3.jpg; FullSizeRender 4.jpg; FullSizeRender5.jpg; FullSizeRender6.jpg; C-141 Initial - 75 BPW spill off Hackberry 7_15_15.doc

Please see attached C-141, map, and pics of the spill occurring near the Hackberry 16 SWD 1 on 7/15/15. Thank you.

Denise Menoud

Admin Field Support 4 / Completions
Devon Energy Production Co. LP/Artesia NM
Denise.Menoud@dvn.com
575-746-5544

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.