

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1520938509		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company Cimarex Energy		162683		Contact Christine Alderman	
Address 600 N Marienfeld Ste 600 Midland TX				Telephone No. 432-853-7059	
Facility Name Pavo Mesa 30 Fed Com 1				Facility Type production	
Surface Owner BLM		Mineral Owner		API No. 30-015-35918	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	30	16S	29E	1780	N	330	W	Eddy

Latitude 32.89514 Longitude -104.120208

NATURE OF RELEASE

Type of Release oil	Volume of Release 12 bbls	Volume Recovered 11 bbls
Source of Release tank	Date and Hour of Occurrence 07/16/15	Date and Hour of Discovery 07/16/15
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson/Jim Amos	
By Whom? Christine Alderman	Date and Hour 07/17/15 10:15 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT
JUL 27 2015

Describe Cause of Problem and Remedial Action Taken.*

Production was routed into a tank that was out of service due to a hole in the tank.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*

All fluids were contained within the LINED berm. Impacted soils on top of the liner will be removed and replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Christine Alderman		OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman		Approved by Environmental Specialist: [Signature]	
Title: ESH Supervisor		Approval Date: 7/28/15	Expiration Date: N/A
E-mail Address: calderman@cimarex.com		Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 07/17/15 Phone: 432-853-7059			

* Attach Additional Sheets If Necessary

2RP-3162

Patterson, Heather, EMNRD

From: Christine Alderman <calderman@cimarex.com>
Sent: Monday, July 27, 2015 12:49 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Subject: FW: Pavo Mesa 30 Fed Com 1 (30-015-35918)

C-141 for the above named release.

Thank you!

Christine Alderman

ESH Supervisor ~ Permian Basin

Mobile: 432-853-7059

Office: 432-620-1982



From: Christine Alderman
Sent: Friday, July 17, 2015 10:24 AM
To: mike.bratcher@state.nm.us; Patterson, Heather, EMNRD (Heather.Patterson@state.nm.us); Amos, James A (jamos@blm.gov)
Subject: Pavo Mesa 30 Fed Com 1 (30-015-35918)

All,

We had a release at the above named facility on 7/16/15. Production was turned into a tank which was out of service due to a hole in the tank. 12 bbls of oil was released into a LINED containment. We were able to recover 11 bbls, there was dirt on top of the liner which will be removed and disposed of.

A c-141 will follow.

Christine Alderman

ESH Supervisor ~ Permian Basin

Mobile: 432-853-7059

Office: 432-620-1982

