

District I  
1625 N. French Dr., Hobbs, NM 88249  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis  
Santa Fe, NM 87505

**RECEIVED**  
SEP 06 2013  
NMOCD ARTESIA

**RECEIVED**  
SEP 06 2013  
NMOCD ARTESIA

Form C-141  
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

Initial Report     Final Report

Name of Company <b>Great Western Drilling Co</b>	Contact <b>Dennis Pender</b>
Address <b>PO Box 1659 Midland, TX 79702</b>	Telephone No. <b>432-682-5241</b>
Facility Name <b>Coats Comm #1</b>	Facility Type <b>Oil Tank</b>
Surface Owner <b>Wayne Neatherlin</b>	Mineral Owner <b>Various</b> API No. <b>30-015-33409</b>

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	19	18S	26 E	990'	North	990'	East	Eddy

Latitude N 32.73901 Longitude W-104.41576

#### NATURE OF RELEASE

Type of Release <b>Condensate</b>	Volume of Release <b>180 bbls</b>	Volume Recovered <b>0</b>
Source of Release <b>Oil Tank</b>	Date and Hour of Occurrence <b>Unknown</b>	Date and Hour of Discovery <b>30Dec12</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Sherry Bonham</b>	
By Whom? <b>Sam Roberts</b>	Date and Hour <b>3Jan12 @ 1230 hrs</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	

If a Watercourse was Impacted, Describe Fully.\*  
**N/A**

Describe Cause of Problem and Remedial Action Taken.\*  
**Valve and Tee froze and burst, allowing condensate to drain from tank.**

Describe Area Affected and Cleanup Action Taken.\*  
**The impacted area (25' x 25' x 12') behind the tanks was excavated with the impacted soil being land farmed on site. The land farmed soil was periodically tilled and turned to allow the light hydrocarbons to "flash off". After a period of approximately 6 months, soil samples of the land farmed soil and the excavation were obtained and lab analysis conducted. Results were presented to NMOCD's Mike Bratcher for closure approval. Approval was given and the excavation was backfilled with the land farmed material.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<p>Signature: <i>Dennis Pender</i></p> <p>Printed Name: Dennis Pender</p> <p>Title: <i>Purchasing Manager</i></p> <p>E-mail Address: dpender@gwdc.com</p> <p>Date: 27Aug13      Phone: 432-682-5241</p>	<p><b>OIL CONSERVATION DIVISION</b></p> <p>Approved by Environmental Specialist: <i>[Signature]</i></p> <p>Approval Date: <i>7/15/15</i>      Expiration Date: <i>NA</i></p> <p>Conditions of Approval: <i>Final</i>      Attached <input type="checkbox"/></p>
---	---

\* Attach Additional Sheets If Necessary

2RP-1023