

NM OIL CONSERVATION

ARTESIA DISTRICT

AUG 7 2015

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Enterprise Field Services LLC	Contact	Dina Ferguson
	PO Box 4324, Houston, TX 77210	Telephone No.	210-528-3824
Facility Name	Pipeline ROW, 30137 Gathering Lateral	Facility Type:	Gas Gathering Pipeline
Surface Owner	State of New Mexico	Mineral Owner	NA - Pipeline
		Lease No.	NA

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	14	19S	28E	34	South	508	East	Eddy

Latitude: N 32.653687 Longitude: W -104.144786

NATURE OF RELEASE

Type of Release	Hydrostatic test Water	Volume of Release:	300 BBL water in use for hydrostatic test	Volume Recovered:	N/A
Source of Release	Pipeline Leak	Date and Hour of Occurrence	07/28/2015 @ 10:00 MDT	Date and Hour of Discovery	07/28/2015 @ 10:00 MDT
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD District 2		
By Whom?	Osman De Leon	Date and Hour	07/28/2015 @ 17:00 MDT		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

During hydrostatic testing of the new pipeline to be installed at the 30137 lateral, the new line failed the test and approximately 200 to 300 bbls of hydrostatic test water spilled to the ground within pipeline Right of Way. The tested pipeline is new, fresh water was used and no hydrocarbon contamination is expected. Samples of the source water were collected. Enterprise is currently investigating this event and will update NMOCD with additional information.

Describe Area Affected and Cleanup Action Taken.*

Liquid spill occurred within pipeline ROW. Any necessary clean-up activities will be carried out in accordance with Enterprise's General release Notification, Response and Remediation Plan (dated March 9, 2015).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jon E. Fields	Approved by District Supervisor:	
Title: Director, Field Environmental	Approval Date: 8/10/15	Expiration Date: N/A
E-mail Address: jefields@eprod.com	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 8-7-2015 Phone: 713-381-6684	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 9/11/15

2RP-3193

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Mendez, Brenda <BJMendez@eprod.com>
Sent: Friday, August 07, 2015 8:01 AM
To: Bratcher, Mike, EMNRD
Subject: Eddy County 30137 Gathering Lateral (C-141 Form)
Attachments: Eddy County C-141 Release Report 30137 (7-28) August 2015.pdf

Attached for your review and handling is the Release Notification & Corrective Action Form for the 30137 Gathering Lateral in Eddy County, NM.

Should you need additional information, please contact Ms. Dina Ferguson at 210-528-3824.

Thank you

Brenda J. Mendez – Planning and Reports Analyst

Enterprise Products Operating, LLC
Tel (713) 381-8270 – Fax (713) 880-6660
bjmendez@eprod.com

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.