

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NABI522256800 **14744** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas	
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905	
Facility Name: Santo Nino 29 Fed SWD #1 #5*	Facility Type: Producing Oil Well	
Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-28689

***SWD is marked as #5** **LOCATION OF RELEASE** **30-015 28689**

Unit Letter G	Section 29	Township 18S	Range 30E	Feet from the 1932'	North/South Line North	Feet from the 1923'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.720294 Longitude -103.992032

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 1170 bbls	Volume Recovered: 1170 bbls
Source of Release: Water Tank	Date and Hour of Occurrence 6-13-15 6:30 pm	Date and Hour of Discovery 6-13-15 7:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos (BLM)	
By Whom? Robin Terrell	Date and Hour 6-14-15 11:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

NM OIL CONSERVATION
ARTESIA DISTRICT

AUG 10 2015

Describe Cause of Problem and Remedial Action Taken.*

RECEIVED

Cause of leak: The tank battery was struck by lightning. Upon being struck, the battery caught fire and burned a hole in the corner of the containment. Fire department was immediately contacted and vacuum trucks arrived to clean the spill as soon as the location was deemed safe.

Describe Area Affected and Cleanup Action Taken.*

Affected area: The produced water leaked out of the SW corner of the containment behind location. Vacuum trucks recovered all of the standing water and any visually contaminated soil was taken to an approved NMOCD disposal site. Final remediation will be conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Z. Thomas	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: [Signature]	
Title: Environmental Rep.	Approval Date: 8/10/15	Expiration Date: NA
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:	
Date: 6-18-15	Phone: 575-602-2188	
Remediation per O.C.D. Rules & Guidelines		

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 9/11/15

2RP-3194

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Patterson, Heather, EMNRD
Sent: Monday, August 10, 2015 9:16 AM
To: zthomas@mewbourne.com
Cc: Bratcher, Mike, EMNRD
Subject: Santa Nino #1 SWD lightning strike

Zack,

On June 16th you reported a lightning strike at the Santa Nino #1 SWD. The OCD has not yet received a C-141 for this event. Please submit one as soon as you can.

Thanks,

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

ENVIRONMENTAL RELEASE NOTIFICATION

Call-In Sheet

Date: _____

Notice received by: HWP

Robert Membrane
Name of Company/Phone #

SWD Santitas #1
Facility Name
Santa Nino?

API # Sec. Township Range Date of Occurrence 9/13

6/13 Flare ? ?
Date/Hour of Discovery Type of Release Volume of Release Volume Recovered

Briefly Describe Cause of Problem and action taken: Flare @ SWD
lightening strike

Notice given by: Name/ Company Date/Hour Immediate Notice given

Date C-141 received: _____ 2RP- _____

FLARE NOTIFICATION

Call-In Sheet

Date: _____

Name of Company/Phone #

Date of Occurrence Date/Hour of Flare

Flared MCF Volume Volume Recovered

Briefly Describe Cause of Problem and action taken: _____

Notice given by: Name/ Company Date/Hour Immediate Notice given

Date C-141 received: _____ 2RP- _____

Santa Nino 29 Feb
SWD #1 015-42534
no entries