District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011 Shmit 1 Copy to appropriate District Office in

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action													
NAB 1526056410						OPERAT	OR	⊠ Initia	l Report	П	Final Report		
Name of Company: BOPCO, L.P.						Contact: Amy Ruth							
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220						Telephone No. 575-887-7329							
Facility Name: Indian Flats Bass Federal #1 Tank Battery (located 2996 ft. SW of Well #1 API 30-015-24968)						Facility Type: Exploration and Production							
Surface Ow	ner: Fede	ral	Mineral O	wner:	: Federal			API No. 30-015-24968					
					N OF DELEASE								
Unit Letter	Section	Township	Range	Feet from the		N OF RELEASE h/South Line Feet from the			East/West Line County				
J	35	21S	38E	recention the	Notalli	South Line	r cet noin the	Lasu	Vest Ellie	Eddy			
<u> </u>		<u> </u>	<u> </u>										
	Latitude 32.43400° Longitude -104.05580°												
NATURE OF RELEASE													
Type of Relea		uced Water			Volume of Release 7 bbls			Volume Recovered 2 bbls					
Source of Ro	lease 2":	fitting on line			Date and Hour of Occurrence 9/3/2015 time unknown			Date and Hour of Discovery 9/3/2015 time unknown					
Was Immediate Notice Given?						If YES, To Whom?					<u> </u>		
☐ Yes ☒ No ☐ Not Required													
By Whom? N/A						Date and Hour N/A							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
						N/A							
If a Watercourse was Impacted, Describe Fully.* ARTESIA DISTRICT													
Describe Cause of Problem and Remedial Action Taken.* SEP 1 4 2015											15		
A 2" fitting failed on the line going from the heater treater to the produced water tanks.													
										RECE	-T) /C-D		
				RECEIVED)				
		and Cleanup											
The leak affe	cted 650 sq	uare feet of c	aliche pad	within the area of	the eart	hen containn	ent. Standing flu	uids wer	e recovered	l.			
				e is true and comp nd/or file certain r									
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
		ws and/or reg		otance of a C-141	report d	oes not reliev	e the operator of	respons	ibility for c	ompiiance v	vith any	other	
Todara, otaco,			, 1		OIL CONSERVATION DIVISION						***		
Signature: Juny						Approved by Environmental Specialist:							
Printed Name	e: Amy Ru	orth		Approved by	Environmental S	specialis	19/4	100	<u> </u>				
Title: Assisi	ant Remed	iation Forema			Approval Date: 9117115 Expiration Date: NIA								
E-mail Addre	ess: ACR	uth@basspet.	com			Conditions o	* *			Attached			
Date: 9/14/2015 Phone: 432-661-0571 Premediation per O.C.D. Rules & Guidelines												Ì	
Attach Addi		ets If Necess		· · · · · · · · · · · · · · · · · · ·	SI	UBMIT RE	MEDIATION	PROP	OSAL N	0	701	-3260	
						ATER THA	N:	abli			W	~0400	

Patterson, Heather, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>

Sent: Monday, September 14, 2015 2:43 PM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

Cc: jamos@blm.gov

Subject: Initial C-141 Indian Flats Bass Federal #1 Tank Battery 9-3-15

Attachments: Indian Flats Bass Federal #1 Tank Battery 9-3-15 Initial C-141.pdf

Hey everyone, had a 7 bbl spill within the earthen containment. Here is the documentation. Please call me with any questions/concerns. Thanks so much ©



Amy C. Ruth
BOPCO, L.P.
EH&S Remediation Specialist
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office: (575)887-7329

Fax: (575)887-7473 Cell: (432)661-0571