

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 16 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1526436708 **ALD737** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV BS 008H	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner:	API No. 3001539508
------------------------	----------------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	14	25S	30E	300		1980		Eddy

Latitude: 32.124005 Longitude: 103.853969

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 49 barrels	Volume Recovered: 48 barrels
Source of Release: Packing gland failed on triplex pump	Date and Hour of Occurrence 9-15-15 @ 12:00pm	Date and Hour of Discovery 9-15-15 @ 12:15pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Bradley Blevins	Date and Hour: 9-15-15 12:44pm * e-mail 8:23am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Packing gland on triplex pump failed, causing fluid to enter impervious containment. The containment failed on the east side and released one barrel of produced water. A vacuum truck was called to the location and recovered 48 barrels of PW from the containment.

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck was called to the location and recovered 48 barrels of PW from the containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Signed By <u>M. L. Bratcher</u> Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: <u>9/21/15</u>	Expiration Date: <u>NA</u>
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>9-16-15</u> Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/22/15

2RP-3271

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Wednesday, September 16, 2015 11:39 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Cherry, Tracie J.; Amos, James
Subject: Initial C-141 PLU CVX JV BS 008H
Attachments: doc04585520150916103523.pdf

Mike/ Heather,

Please find the attached initial C-141 for the release that occurred at the PLU CVX JV BS 008H. If you have any questions please let me know.

Thank you

Brad Blevins
Remediation Foreman (PLU)
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Tuesday, September 15, 2015 8:23 AM ✱
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Blevins, Bradley
Subject: PLU CVX JV BS 008H Release
Attachments: photo 2.jpg; photo 3.jpg; photo 5.jpg

Mike/ Heather

BOPCO EHS was notified of a release that occurred on the PLU CVX JV BS 008H, a packing gland on the triplex pump failed and released fluid to the lined containment. A vacuum truck recovered all fluid from inside the containment (48 barrels), the containment had a small hole on the east side and about one barrel leaked out to the well pad. Can I send in one C-141 with initial and final? Please let me know if you have any questions. Thank you.

Brad Blevins
Remediation Foreman (PLU)
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com