

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 22 2015

Form C-141  
Revised August 8, 2011

RECEIVED to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

NAB1526657039

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 153	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 3001531412
------------------------	------------------------	--------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	6	24s	30E	1830		1980		Eddy

Latitude: 32.248582 Longitude: 103.918065

### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 15 barrels	Volume Recovered: 5 barrels
Source of Release: Swedge on produced water tank	Date and Hour of Occurrence: 9-18-15 @ 1:00pm	Date and Hour of Discovery: 9-18-15 @ 1:30pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

BOPCO EHS was notified of a spill that occurred when a pin hole developed in the swedge of the produced water tank load line. A vacuum truck was called to the location and recovered 5 barrels from within the earth berm.

Describe Area Affected and Cleanup Action Taken.\*

A vacuum truck was called to the location and was able to recover 5 barrels of produced water from within the earth berm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: <u>Bradley Blevins</u>	SIGNED BY <u>Mike Brannon</u>	
Printed Name: Bradley Blevins	Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 9/23/15	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9-22-15 Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 10/25/15

200.3293

\* Attach Additional Sheets If Necessary

**Bratcher, Mike, EMNRD**

---

**From:** Blevins, Bradley <BBlevins@BassPet.Com>  
**Sent:** Tuesday, September 22, 2015 8:42 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James  
**Cc:** Blevins, Bradley  
**Subject:** Initial C-141 PLU 153  
**Attachments:** doc04598420150922073514.pdf

All,

Please find the attached initial C-141 for the spill that occurred at the PLU 153 battery. If you have any questions please let me know.

Thanks

Brad Blevins  
Remediation Foreman (PLU)  
BOPCO, LP  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office-575-887-7329  
Cell-1-432-214-3704  
bblevins@basspet.com