

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

x Initial Report ☐ Final Report

Name of Company Plains Pipeline #231735	Contact Camille Reynolds
Address 3112 W. US Hwy 82, Lovington, NM 88260	Telephone No. 505-441-0965
Facility Name North Hobbs 8 Inch	Facility Type 8" Steel Pipeline

Surface Owner R,M and S Enterprises	Mineral Owner	Lease No.
-------------------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter M	Section 29	Township 18S	Range 38E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32° 42' 40.2" Longitude 103° 10' 41.7"

40'

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 10 barrels	Volume Recovered 3 barrels
Source of Release 8" Steel Pipeline	Date and Hour of Occurrence 2-09-06 @ 9:00	Date and Hour of Discovery 2-09-06 @ 10:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Camille Reynolds	Date and Hour 2-09-06 @ 11:00	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* Internal corrosion of a 8 inch steel pipeline resulted in a release of sour crude oil. A clamp was installed on the line to mitigate the release. The line is a 8 inch steel gathering pipeline that produces approximately 200 barrels of crude oil per day. The pressure on the line is approximately 20 psi and the gravity of the sour crude oil is 37. The sour crude has an H<sub>2</sub>S content of <10 ppm. The line was approximately 1.5 feet bgs at the release point.

Describe Area Affected and Cleanup Action Taken.\* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was approximately 400 ft<sup>2</sup>.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Camille Reynolds</i>	OIL CONSERVATION DIVISION	
Printed Name: Camille Reynolds	Approved by District Supervisor:	
Title: Remediation Coordinator	Approval Date:	Expiration Date:
E-mail Address: cjreynolds@paalp.com	Conditions of Approval:	Attached <input type="checkbox"/>

Plains - 231735  
Facility - PPAC0605427863

Phone: 505 441 0965

incident - PPAC0605428054  
application - PPAC0605428301