

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☐ Final Report

Name of Company: Range Operating, New Mexico	Contact: Steve Almager
Address: Po Box 2510, Hobbs, NM 88240	Telephone No. 505-394-1485
Facility Name: Grizzell A Battery	Facility Type: Battery

Surface Owner Wayne Henson	Mineral Owner (Attached)	Lease No. 301560
----------------------------	--------------------------	------------------

LOCATION OF RELEASE

Unit Letter H	Section 6	Township 22s	Range 37e	Feet from the 1650	North/South Line North	Feet from the 330	East/West Line East	County Lea
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Oil and Water	Volume of Release: 15 bbls	Volume Recovered: 13 Bbls
Source of Release: Oil Tank	Date and Hour of Occurrence: 2-15-06 10:00 am	Date and Hour of Discovery: 2-15-06 10:25am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Bryan Surles and Linda Stiles	
By Whom? Steve Almager	Date and Hour 2-15-06 1030 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Water Leg on Heater Plugged off, dumped water and oil into oil tank causing it to overflow.

Water leg unplugged and put back into operation, while monitoring heater

Describe Area Affected and Cleanup Action Taken.*

13 bbls of oil and water contained inside 40 mil lined firewalls and removed with a vacuum truck. 40 x 50 area on east side of battery misted with oil. Ocotillo Environmental will remove soil and pea gravel from battery and replace with new. 40 x 50 area outside of firewall will be treated with micro blaze periodically until vegetation is clean.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Steve Almager

Printed Name: Steve Almager

Title: Production Supervisor

E-mail Address: Salmager@rangeresource.com

Date: 2-16-2006

Phone: (817) 810-1908

Approved by District Supervisor:

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

Range - 227588

facility - P PAC 0605432765

incident - n PAC 0605432837
application - P PAC 0605433074