


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	John H. Hendrix Corp.	Contact	Marvin Burrows
Address	P.O. Box 910, Eunice, N.M.	Telephone No.	505-394-2649
Facility Name	Thomas Long A-3	Facility Type	Well Flowline
Surface Owner	Lavin Boyo	Mineral Owner	N.M.
		Lease No.	3002534033

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	11	22S	37E	1320'	5	660'	W	Lea

Latitude 32°24'06.8" Longitude 103°08'20.3"

NATURE OF RELEASE

EST 50 + BEU 39

Type of Release	oil/gas/water	Volume of Release	20	Volume Recovered	0
Source of Release	Flowline	Date and Hour of Occurrence	2/1/06	Date and Hour of Discovery	2/2/06 12 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required				
By Whom?	Marvin Burrows	Date and Hour	3:00 PM 2/2/06		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Hole in 3" Steel Flowline

Describe Area Affected and Cleanup Action Taken.*

Irregular Area Running N/S. Approx.
3,320 SQ. FT.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Marvin Burrows	OIL CONSERVATION DIVISION	
Printed Name: MARVIN BURROWS	Approved by District Supervisor:	
Title: PROD. MGR.	Approval Date:	Expiration Date:
E-mail Address: MBURROWS@VALON.NET	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/2/06 Phone:		

* Attach Additional Sheets If Necessary 505-394-2649

John Hendrix - 12024
incident - nPAC 0603845973
application - nPAC 0606231982

John H. Hendrix, Corp.
PO Box 910
Eunice, NM 88231
505-394-2649

2/2/06

Attn :
Paul Sheeley
OCD
Hobbs, NM

Dear Paul :


Please find with this fax a form C-141 concerning an accidental release we had on our Thomas Long A # 3 flowline. As you know, we are currently cleaning up an earlier release from this line. The new release is about 120 yds. due south of the one we are now working on.

The land owner is Irvin Boyd. I have been in contact with him. He knows what happened, and knows what we are doing to take care of it.

We have the situation stabilized, and have replaced the old line with a new 2" poly pipe flowline. Mark Larson will be in Eunice Friday morning (2/3/06) to look the site over, and will formulate a cleanup plan. We will keep you posted at all times.

Please call with any questions or concerns.

Sincerely,



Marvin Burrows

Prod. Mgr.

JHH, Corp., Eunice, NM

Cell : 505-390-9689