

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
10 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Doyle Hartman Oil Operator	Contact	Don Mashburn
Address	500 N. Main St.	Telephone No.	432-684-4011
Facility Name	State "LMT" #9	Facility Type	Gas Well

Surface Owner	State of New Mexico	Mineral Owner	State of New Mexico	Lease No.	B-1431
---------------	---------------------	---------------	---------------------	-----------	--------

LOCATION OF RELEASE

API # 30025266160000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	36	23-S	36-E	780'	FNL	1860'	FWL	Lea County, NM

Latitude 32.26602 Longitude -103.22106

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	149 BBLs	Volume Recovered	10 BBLs
Source of Release	300 BBL Fiberglass Tank	Date and Hour of Occurrence	6/3/05 @ 12:30 am	Date and Hour of Discovery	6/3/05 @ 12:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mr. Buddy Hill - NMOCD		
By Whom?	Rick Wilson	Date and Hour	6/3/05 @ 1:35 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

From Electrical Storm, Lightning hit the 300 BBL Produced Water Tank causing the top and bottom to be separated from tank body.

Describe Area Affected and Cleanup Action Taken.*

The berm was breached and water & a trace of oil flowed off location down the ditch of the lease road. Rick Wilson called Pulfer Vacuum truck (Jal, NM) to vacuum up any pooled water & oil. Also called EPI (Environmental Plus Inc.) of Eunice, NM to check for soil samples and clean up recommendation. Replaced 300 BBL tank with new tank.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Don Mashburn*

Printed Name: Don Mashburn

Title: Engineer

E-mail Address: dhoo-dm@swbell.net

Date: 6/6/05

Phone: 432-684-4011

Approved by District Supervisor:

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

incident - NARS 0518135656
application - PPA 0607437394