

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

OCT 12 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

1 JMW 1322134908
0 AB1529327911

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Enterprise Field Services LLC	Contact	Dina Ferguson
	PO Box 4324, Houston, TX 77210	Telephone No.	210-528-3824
Facility Name	Pipeline ROW, D-3 Line	Facility Type:	Gas Gathering Pipeline
Surface Owner	State of New Mexico	Mineral Owner	NA - Pipeline
		Lease No.	NA

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	15	19S	29E	108	South	555	East	Eddy

Latitude: N 32.653728 Longitude: W -104.064558

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release:	297 MCF	Volume Recovered:	N/A
Source of Release	Pipeline Leak.	Date and Hour of Occurrence	10/08/2015 @ 02:30 MDT	Date and Hour of Discovery	10/08/2015 @ 02:30 MDT
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Pipeline leak caused by a truck driver running over pipeline tie-in. Pipeline segment was clamped and blown down, and leaking portion was repaired.					
Describe Area Affected and Cleanup Action Taken.*					
No liquid spills occurred requiring any cleanup actions.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 	
Printed Name: Jon E. Fields	Approval Date: 10/20/15	Expiration Date: N/A
Title: Director, Field Environmental	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
E-mail Address: jefields@eprod.com		
Date: 10-12-2015 Phone: 713-381-6684		

* Attach Additional Sheets If Necessary

2RP-3340

Bratcher, Mike, EMNRD

From: Nolan, Shiver <SNolan@eprod.com>
Sent: Monday, October 12, 2015 9:23 AM
To: Bratcher, Mike, EMNRD
Cc: Ferguson, Dina; DeLeon, Osman
Subject: Eddy County D-3 Line
Attachments: Eddy County C-141 (Final) D-3 Line (10-8) October 2015.pdf

Attached is the subject report. Should you need additional information, please contact Dina Ferguson at 210-528-3824.

Shiver Nolan
Sr. Compliance Administrator

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.