District 1 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

FAB1529341828

DAB1524342407

Bureau of Land

Jon E. Fields

Date: 10-14-2015 Phone: 713-381-6684 * Attach Additional Sheets If Necessary

E-mail Address: jeflelds@eprod.com

Director, Field Environmental

Printed/Na

Title:

Facility Name Surface Owner

Management

NM OIL CONSERVATION

ARTESIA DISTRICT

OCT 19 2015

Initial Report

Lease No.

Signed By Mile Drameder

FINAL

Expiration Date:

Attached

2RP-3346

Form C-141 Revised August 8, 2011

Final Report

Submit 1 Copy to appropriate District Office in RECEIVE& Structure with 19,15.29 NMAC.

NA

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 **Release Notification and Corrective Action OPERATOR** Name of Company Enterprise Field Services LLC Contact Dina Ferguson PO Box 4324, Houston, TX 77210 Telephone No. 210-528-3824 Facility Type: Gas Gathering Pipeline Pipeline ROW, OMYOMZ Line Mineral Owner NA - Pipeline

State of New Mexico

Energy Minerals and Natural Resources

LOCATION OF RELEASE Unit Letter Feet from the North/South Line East/West Line Section Feet from the County Township Range H 29Ē 89 33 23S North 508 East Eddy

Latitude: <u>N 32.264699</u>

Longitude: W-103.982774

Approved by District Supervisor:

Approval Date: 10

Conditions of Approval:

NATURE OF RELEASE		
Type of Release Natural Gas	Volume of Release: 103 MCF	Volume Recovered: N/A
Source of Release Pipeline Leak.	Date and Hour of Occurrence	Date and Hour of Discovery
······································	10/11/2015 @ 11:30 MDT	10/11/2015 @ 11:30 MDT
Was Immediate Notice Given?	If YES, To Whom?	
□ Yes □ No ⊠ Not Required		-
By Whom?	Date and Hour	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
🗋 Yes 🖾 No		
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
Pipeline leak detected by driver passing by, Pipeline segment was clamped and blown down, and leaking portion was repaired.		
Describe Area Affected and Cleanup Action Taken.*		
No liquid spills occurred requiring any cleanup actions.		
I hereby certify that the information given above is true and complete to the regulations all operators are required to report and/or file certain release no public health or the environment. The acceptance of a C-141 report by the should their operations have failed to adequately investigate and remediate or the environment. In addition, NMOCD acceptance of a C-141 report do federal, state, or local laws and/or regulations.	otifications and perform corrective ac NMOCD marked as "Final Report" contamination that pose a threat to goes not relieve the operator of response	tions for releases which may endanger does not relieve the operator of liability round water, surface water, human health sibility for compliance with any other
Signature: Jan Fulls		ATION DIVISION

Bratcher, Mike, EMNRD

From:	Nolan, Shiver <snolan@eprod.com></snolan@eprod.com>
Sent:	Monday, October 19, 2015 2:59 PM
То:	Bratcher, Mike, EMNRD
Cc:	Randy Pair (rpair@blm.gov)
Subject:	OMYOMZ Line - October 11
Attachments:	Eddy County C-141 OMYOMZ Line (10-11) October 2015.pdf

Attached for your review and handling is the C-141 (initial and final report) for the subject release.

Shiver J. Nolan Sr. Compliance Administrator Enterprise Products Operating LLC

.

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.