

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	St Mary Land & Exploration Co.	Contact	Donna Huddleston
Address	3300 N. A Street, Bldg. 7, Ste. 200, Midland, TX 79705	Telephone No.	432-688-1789
Facility Name	Tirano CNG State	Facility Type	Tank Battery
Surface Owner	State of New Mexico	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	36	24E	28E	660	South	1980	West	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	20bbls	Volume Recovered	2bbls
Source of Release	4' x 20' Heater treater	Date and Hour of Occurrence	1/19/2009	Date and Hour of Discovery	1/19/09 1:00am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher w/NMOCD (left voicemail)		
By Whom?	Bill Hearne	Date and Hour	1/19/09 11:07am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Cause: Heater treater dump failure. Oil dump failed to operate properly, filled gas section of heater treater and dumped oil out of gas vent line. Repair oil dump on heater treater and return wells to production. Vacuum truck picked up approx. 2bbls off ground

Describe Area Affected and Cleanup Action Taken.*

Affected area: 30'x30' @vent line and 300'x 12' South of vent. Total area 4800 sq.ft. in pasture.
Cleanup Action Taken: Washed down treater and used vacuum truck to pick up oil.
Soils were excavated by Tetra Tech and hauled off for proper disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Tim Reed (agent for St. Mary Land)	Approved by District Supervisor: 	
Title: Tetra Tech	Approval Date: 10/5/10	Expiration Date: N/A
E-mail Address: timothy.reed@tetratech.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 10/22/2009 432-682-4559		

* Attach Additional Sheets If Necessary

2RP-294