District 1 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141 NOV 1 3 2015 Revised August 8, 2011

**Oil Conservation Division** 1220 South St. Francis Dr. Santa Fe, NM 87505

State of New Mexico

**Energy Minerals and Natural Resources** 

Submit 1 Copy to appropriate District Office in RECEIVED rdance with 19.15.29 NMAC.

NA

Lease No.

FAB 1532050503 Release Notificati	ion and Corrective Actio	)n	
NAB1532050629	OPERATOR	🛛 Initial Report	Final Report
Name of Company Enterprise Field Services LLC	Contact Alena Polk		
PO Box 4324, Houston, TX 77210	Telephone No. 575-706-4926		
Facility Name Pipeline ROW, Baldridge Canyon 583630W8	Facility Type: Gas Gathering	Pipeline	

Surface Owner State of New Mexico Mineral Owner NA - Pipeline

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	11	24S	24E	238	South	195	East	Eddy

Latitude: <u>N 32.23246</u>

Longitude: <u>W-104,46976</u>

## NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release: 51 MCF	Volume Recovered: N/A		
Source of Release Pipeline Leak	Date and Hour of Occurrence 11/07/2015 @ 13:30 MST	Date and Hour of Discovery 11/07/2015 @ 13:30 MST		
Was Immediate Notice Given?	If YES, To Whom?			
By Whom?	Date and Hour			
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*				
Describe Cause of Problem and Remedial Action Taken.*				
Pipeline leak was detected by a pipeline technician. Pipeline segment was isolated and blown down. Pipeline repair will be made following standard one-call. No liquids noted.				
Describe Area Affected and Cleanup Action Taken.*				
No liquid spills occurred as part of the leak. No remediation actions were necessary.				
I hereby certify that the information given above is true and complete to 1 regulations all operators are required to report and/or file certain release republic health or the environment. The acceptance of a C-141 report by the should their operations have failed to adequately investigate and remediat or the environment. In addition, NMOCD acceptance of a C-141 report of federal, state, or local laws and/or regulations.	notifications and perform corrective ac a NMOCD marked as "Final Report" te contamination that pose a threat to g	tions for releases which may endanger does not relieve the operator of liability ground water, surface water, human health		
Signature: Jon Fuelde		VATION DIVISION		
Printed Name, Jon E. Fields	Approved by District SayeryispBy	BAIly Brenoredise		
Title: Director, Field Environmental	Approval Date: 111015	Expiration Date: N/A		
E-mail Address: jefields@eprod.com Date: //-/3-20/5 Phone: 713-381-6684	Conditions of Approval: FINA	Attached 🗆		
Attach Additional Sheets If Necessary		020 2200		

2KP-334

## Bratcher, Mike, EMNRD

From:	Nolan, Shiver <snolan@eprod.com></snolan@eprod.com>	
Sent:	Friday, November 13, 2015 10:35 AM	
То:	Bratcher, Mike, EMNRD	
Cc:	Polk, Alena; Ferguson, Dina	
Subject:	Eddy County C0141 Baldridge Canyon	
Attachments:	Eddy County C-141 Baldridge Canyon (11-7) November 2015.pdf	

. .

•

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.

.