District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

FAB1432841543 NAB1532130874

\* Attach Additional Sheets If Necessary

## State of New Mexico **Energy Minerals and Natural Resources**

accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

**Release Notification and Corrective Action** 

**OPERATOR** 

Submit 1 Copy to appropriate District Office in

Form C-141

Final Report

Revised August 8, 2011

Name of Co	mpany $E$	ces L	LC	Contact Dina Babinski								
							Telephone No. 210-528-3824					
							Facility Type: Gas Gathering Pipeline					
Surface Owner State of New Mexico Mineral Owner							NA - Pine	NA - Pipeline Lease No. NA				
	LOCATION OF RELEASE											
Unit Letter							n/South Line					
SWSE 13 19S 28E 30							South	547		West	Eddy	
Latitude: <u>N 32.653815</u> Longitude: <u>W -104.128657</u>												
NATURE OF RELEASE												
Type of Release Natural Gas, Pipeline Liquids							Volume of Release: 1647 MCF, 1 Volume Recovered: N/A					
Source of Release Pipeline Leak.								BBL Liquids  Determine the second through Discourses				
Source of Resease Pipeline Leak.								Date and Hour of Occurrence Date and Hour of Discovery 11/08/2014 @ 09:40 MST 11/08/2014 @ 09:40 MST				
Was Immediate Notice Given?								If YES, To Whom?				
☐ Yes ☐ No ☐ Not Required							Mike Bratcher, District 2					
By Whom? Osman De Leon							Date and Hour 11/08/2014 @ 13:02 MST					
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.  NM OIL CONSERVATION					
☐ Yes ☒ No							ARTESIA DISTRICT					
If a Watercou	irse was Im	pacted, Descr	ibe Fully.	*								
											. NOV <b>20 2014</b>	
Describe Cau	se of Probl	em and Reme	dial Action	n Tak	en.*		<del></del>					
	RECEIVED											
Pipeline leak was detected by a driver passing by. Pipeline segment was clamped and blown down, and leaking portion was repaired.												
Describe Are	a Affected	and Cleanup	Action Tak	cen *								
	Describe Area Affected and Cleanup Action Taken.*  Liquid spill occurred within pipeline ROW. Cleanup activities are currently being performed and additional sampling has been requested to confirm											
cleanup is sa	cleanup is satisfactory.											
	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and											
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state, or local laws and/or regulations.												
(/6//1							OIL CONSERVATION DIVISION					
Signature: /w (, Trucks							01 m 10 m 1/ W					
Printed Name: Jon E. Fields							Approved by District Supervisor Mile Branco					
,							MINIS TO MINISTER					
Title: Director, Field Environmental								Approval Date: \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\				
E-mail Address: jefields@eprod.com							Conditions of	Conditions of Approval:				
Date: 1///4	17014	4										

November 14, 2014

## NM OIL CONSERVATION

ARTESIA DISTRICT

NJV 20 2014

7014 1820 0001 6317 7668 Return Receipt Requested

RECEIVED

Mr. Mike Bratcher New Mexico Oil Conservation Division District 2 Office 811 South First Street Artesia, New Mexico 88210

RE:

Form C-141 Report for Enterprise Field Services LLC Release on Carlsbad Area Gathering Lines

Dear Mr. Bratcher,

Enclosed, please find the required initial C-141 Form report for the unplanned release on our 30137 Line in Eddy County on November 8, 2014.

This report is sent pursuant to NMAC 19.15.29 and as follow-up to verbal notifications made to your office over the phone by Osman De Leon on November 8<sup>th</sup>, 2014 at 1:02 PM MST. Cleanup activities are currently underway, and a final C-141 form will be submitted when soil sampling results demonstrate that cleanup of the affected area is complete.

If you have any questions or need additional information, please contact Dina Babinski, our area Environmental Supervisor at 210-528-3824, or me at 713-381-6684.

Yours truly,

Ion F Field

Director, Field Environmental

/bjm Enclosure