

Sent to NMOCD Dist 2 by
Devon via email 1/23/2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

| | | | | |
|---|--|------------------------------------|--|---------------------------------------|
| nAB1532334246 | | OPERATOR | <input checked="" type="checkbox"/> Initial Report | <input type="checkbox"/> Final Report |
| Name of Company Devon Energy | | Contact Kevin Phillips | | |
| Address PO Box 250 Artesia, NM 88211 | | Telephone No. 575- 748-3371 | | |
| Facility Name Todd 36 I | | Facility Type SWD | | |
| Surface Owner State | | Mineral Owner State | API No. 30-015-20341 | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|-----------|------------|------------|---------------|------------------|---------------|----------------|-------------|
| K | 36 | 23S | 31E | 1980 | WEST | 1980 | NORTH | EDDY |

Latitude: 32.2626871870239 Longitude: 103.733599857938

NATURE OF RELEASE

| | | |
|--|---|---|
| Type of Release Produced Water | Volume of Release 75 BBL | Volume Recovered 50 BBL |
| Source of Release Water tank leak | Date and Hour of Occurrence 1/21/15 2:00PM | Date and Hour of Discovery 1/21/15 2:00 PM |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? BLM- Jeff Robertson OCD- Mike Bratcher | |
| By Whom? Kevin Phillips | Date and Hour 1/22/15 10:15 PM BLM 1/22/15 1:00 PM OCD | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* Hole in water tank. | | |
| Describe Area Affected and Cleanup Action Taken.* Lease operator noticed a hole about 5' from the bottom of the tank. The containment was full and overflowing onto the location. 75 BBL total spill with 50 BBL recovered. Called SB Transportation for a vacuum truck to pick up water. Planning the cleanup with Enviro Clean. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature: <u>Jeanette Barron</u> | OIL CONSERVATION DIVISION | |
| Printed Name: <u>Jeanette Barron</u> | Signed By <u>Mike Bratcher</u> Approved by Environmental Specialist: | |
| Title: <u>Field Admin Support</u> | Approval Date: <u>11/19/15</u> | Expiration Date: <u>N/A</u> |
| E-mail Address: <u>Jeanette.barron@dvn.com</u> | Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO | |
| Date: <u>1.23.15</u> Phone: <u>575-748-1813</u> | LATER THAN: <u>12/19/15</u> | |

* Attach Additional Sheets If Necessary

2RP-3405

Bratcher, Mike, EMNRD

From: Farley, Sandy <Sandy.Farley@dev.com>
Sent: Wednesday, November 18, 2015 9:50 AM
To: Bratcher, Mike, EMNRD
Cc: Fuls, Brett
Subject: Todd 36 State 1 SWD Spill 1.21.15
Attachments: Relayed Todd 36 1 SWD Spill 1.21.15; C-141Todd 36 State 1 SWD.doc

Good morning,

Attached is the Initial C-141 and relay receipt regarding the information sent to you on Friday January 23, 2015 for the 75BBL produced water release that occurred at the Todd 36 State 1 SWD on January 21, 2015.

Please let me know if I can provide any additional assistance.

Have a terrific day

Sandra Farley
Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, New Mexico 88211
575 746 5587



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

Bratcher, Mike, EMNRD

From: Microsoft Outlook
<MicrosoftExchange329e71ec88ae4615bbc36ab6ce41109e@dv.n.com>
To: Mike Bratcher (mike.bratcher@state.nm.us)- OCD Eddy County; Heather Patterson
(heather.patterson@state.nm.us)
Sent: Friday, January 23, 2015 3:09 PM
Subject: Relayed: Todd 36 1 SWD Spill 1.21.15

Delivery to these recipients or groups is complete, but no delivery notification was sent by the destination server:

Mike Bratcher (mike.bratcher@state.nm.us)- OCD Eddy County (mike.bratcher@state.nm.us)

Heather Patterson (heather.patterson@state.nm.us) (heather.patterson@state.nm.us)

Subject: Todd 36 1 SWD Spill 1.21.15