

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1532440540

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Cimaxex Energy 162683	Contact Christine Alderman
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059
Facility Name Secrest Et Al I SWD	Facility Type SWD

Surface Owner private	Mineral Owner	API No. 30-015-22321
-----------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	7	19S	26E	660	N	1980	E	Eddy

Latitude 32.68083 Longitude -104.41922

NATURE OF RELEASE

Type of Release produced water	Volume of Release 20 bbls	Volume Recovered 10 bbls
Source of Release pump	Date and Hour of Occurrence 11/17/2015	Date and Hour of Discovery 11/17/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson	
By Whom? Christine Alderman	Date and Hour 11/18/2015 11:40 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The stainless steel tubing going to the pulsation dampener was broke off from vibration of the triplex pump.

Describe Area Affected and Cleanup Action Taken.*

impact was on the location pad. Samples will be collected and a work plan will be developed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Christine Alderman	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist: 	
Title: ESH Supervisor	Approval Date: 11/20/15	Expiration Date: N/A
E-mail Address: calderman@cimaxex.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: 11/19/2015 Phone: 432-853-7059	LATER THAN: 12/20/15	

* Attach Additional Sheets If Necessary

LATER THAN: 12/20/15

2RP-3408

Patterson, Heather, EMNRD

From: Christine Alderman <calderman@cimarex.com>
Sent: Thursday, November 19, 2015 9:16 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: mburton@diversifiedfsi.com
Subject: FW: Secrest Et Al 1 SWD (30-015-22321)
Attachments: 20151119100623995.pdf

Here is the C-141.

Thank you!

Christine Alderman

ESH Supervisor – Permian Basin

Mobile: 432-853-7059

Office: 432-620-1982



From: Christine Alderman
Sent: Wednesday, November 18, 2015 11:40 AM
To: mike.bratcher@state.nm.us; Patterson, Heather, EMNRD (Heather.Patterson@state.nm.us)
Subject: Secrest Et Al 1 SWD (30-015-22321)

We had a release at the above location 11/17/2015.

Stainless steel tubing going to the pulsation dampener broke from the vibration of the triplex pump.

20 bbls of produced water was released onto the location pad, and 10 bbls were recovered.

A C-141 will follow shortly.

Christine Alderman

ESH Supervisor – Permian Basin

Mobile: 432-853-7059

Office: 432-620-1982

