

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

DEC 02 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

10137

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production Company	Contact	Garry Michael Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-513-4895
Facility Name	Cotton Draw Unit 167H	Facility Type	Oil
Surface Owner	State	Mineral Owner	State
		API No	30-015-41385

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	36	24S	31E	2310	South	2200	West	Eddy

Latitude: N 32°16'71.55"

Longitude: W -103°73'23.14"

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 40bbls	Volume Recovered 38bbls
Source of Release 8 inch water trunk line split	Date and Hour of Occurrence November 30, 2015 1:00 PM	Date and Hour of Discovery November 30, 2015 1:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones, OCD	
By Whom? Matt Nettles, Assistant Production Foreman	Date and Hour December 1, 2015 10:15 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

The water trunk line had an 8" split causing a 40bbls produced water release. The line going to the water trunk was closed, isolated and locked out to prevent further release and repairs have been made to the trunk line.

Describe Area Affected and Cleanup Action Taken.*

The affected area is a 20' x 15' area on the East side of the facility on a Devon right of way. The total release was 40bbls produced water with 38bbls recovered via vacuum truck. Environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Signed By <i>[Signature]</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 12/3/15	Expiration Date: N/A
E-mail Address: Sheila.Fisher@dvn.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	
Date: 12.2.2015 Phone: 575.748.1829	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

DATE THAN: 11/3/10

200-3422

Bratcher, Mike, EMNRD

From: Fisher, Sheila <Sheila.Fisher@devon.com>
Sent: Wednesday, December 02, 2015 1:01 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Fulks, Brett; Nettles, Matt; Michael, Garry; Farley, Sandy
Subject: Cotton Draw Unit 167H_40bbl pw release_11.30.15
Attachments: Cotton Draw Unit 167H_40bbl pw release_Initial C-141_11.30.15.doc; Cotton Draw Unit 167H_40bbl pw release_GIS Image_ 11.30.15.pdf; Cotton Draw Unit 167H_40bbl pw release_photo 1 of 2_ 11.30.15.pdf.jpg; Cotton Draw Unit 167H_40bbl pw release_photo 2 of 2_ 11.30.15.pdf.jpg

Good Morning,

Attached please find the Initial C-141, GIS Image and photo for the 40bbl produced water release at the Cotton Draw Unit 167H on 11.30.15.

If you have any questions please feel free to contact me.

Thank you

Sheila Fisher
Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.