

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1533 752388		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Devon Energy Production		Contact Garry Michael, Production Foreman			
Address 6488 Seven Rivers Hwy Artesia, NM 88220		Telephone No. 575-513-4895			
Facility Name Ross Ranch 10 Fed 1 SWD		Facility Type SWD			
Surface Owner Federal		Mineral Owner Federal		API No. 30-015-29605	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	10	26S	31E	1980	North	660	East	Eddy

Latitude: 32.059235486

Longitude: -103.75905787

NATURE OF RELEASE

Type of Release Produced Water Release	Volume of Release 10bbls	Volume Recovered 8bbls
Source of Release Disposal Pump	Date and Hour of Occurrence November 24, 2015 1:46 PM	Date and Hour of Discovery November 24, 2015 1:46 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson, OCD Jim Amos, BLM	
By Whom? David Washington, Assistant Production Foreman	Date and Hour Heather Patterson, OCD November 24, 2015 1:05 PM Jim Amos, BLM November 24, 2015 1:35 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A


Describe Cause of Problem and Remedial Action Taken.*

A stainless steel fitting on the salt water disposal pump leaked at the connection to the ball valve releasing approximately 10bbls produced water. All valves on the stainless steel line connected to the pump were immediately closed to stop the release. The stainless steel fitting on the salt water disposal pump has been repaired.

Describe Area Affected and Cleanup Action Taken.*

The spill was approximately 10' x 15' area located on the Southwest corner of the location next to the salt water disposal pump. 10bbls produced water was released and 8bbls were recovered with no fluid leaving location. Environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher		OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher		Approved by Environmental Specialist: 	
Title: Field Admin Support		Approval Date: 12/3/15	Expiration Date: N/A
E-mail Address: Sheila.Fisher@dvn.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 12/1/15	Phone: 575.748.1829	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 11/3/16	

* Attach Additional Sheets If Necessary

DEC 02 2015

RECEIVED

22P-3427

Patterson, Heather, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Wednesday, December 02, 2015 9:27 AM
To: Jim Amos (jamos@blm.gov); Shelly Tucker (stucker@blm.gov); Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Fulks, Brett; Washington, David; Farley, Sandy
Subject: Ross Ranch 10 Fed 1 SWD_10bbl pw release_11.24.15
Attachments: Ross Ranch 10 Fed 1 SWD_10bbl PW release_Initial C-141_11.24.15.doc; Ross Ranch 10 Fed 1 SWD_10bbl PW release_GIS Image_11.24.15.pdf; Ross Ranch 10 Fed 1 SWD_10bbl PW release_picture 1 of 7_11.24.15.jpg; Ross Ranch 10 Fed 1 SWD_10bbl PW release_picture 2 of 7_11.24.15.jpg; Ross Ranch 10 Fed 1 SWD_10bbl PW release_picture 3 of 7_11.24.15.jpg; Ross Ranch 10 Fed 1 SWD_10bbl PW release_picture 4 of 7_11.24.15.jpg; Ross Ranch 10 Fed 1 SWD_10bbl PW release_picture 5 of 7_11.24.15.jpg; Ross Ranch 10 Fed 1 SWD_10bbl PW release_picture 6 of 7_11.24.15.jpg; Ross Ranch 10 Fed 1 SWD_10bbl PW release_picture 7 of 7_11.24.15.jpg

Good Morning,

Attached please find the Initial C-141, GIS Image and photo for the 10bbl produced water release at the Ross Ranch 10 Fed 1 SWD on 11.24.15.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

ENVIRONMENTAL RELEASE NOTIFICATION

Call-In Sheet

Date: 11/24/15

Notice received by: HP

Devon 575-513-0071
Name of Company/Phone #

Ross Ranch 10 Fed #1 SWD
Facility Name

API # _____ Sec. _____ Township _____ Range _____ Date of Occurrence _____
Date/Hour of Discovery _____ Type of Release PW Volume of Release 10 bbl Volume Recovered Unkn

Briefly Describe Cause of Problem and action taken: steel line break
all on pad

David Washington 11/24/15 1:20pm
Notice given by: Name/ Company Date/Hour Immediate Notice given

Date C-141 received: _____ 2RP- _____

FLARE NOTIFICATION

Call-In Sheet

Date: _____

Notice received by: _____

Name of Company/Phone #

Facility Name

Date of Occurrence

Date/Hour of Flare

Type of Release

Flared MCF Volume

Volume Recovered

Briefly Describe Cause of Problem and action taken: _____

Notice given by: Name/ Company

Date/Hour Immediate Notice given

Date C-141 received: _____ 2RP- _____