

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

DEC 23 2015

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1535837018

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Garry Michael, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-513-4895
Facility Name	Cotton Draw Unit 65-lease road	Facility Type	Salt Water Disposal

Surface Owner	Federal	Mineral Owner	State	API No.	30-015-10843
---------------	---------	---------------	-------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	2	25S	31E	1980	North	1980	East	Eddy

Latitude: 32.161085918

Longitude: -103.746039442

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	2bbls	Volume Recovered	0bbls
Source of Release	Flow line next to road	Date and Hour of Occurrence	December 22, 2015 1:00 PM	Date and Hour of Discovery	December 22, 2015 1:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos, BLM Mike Bratcher, OCD		
By Whom?	Ray Carter, Assistant Production Foreman	Date and Hour	Jim Amos, BLM December 23, 2015 1:05 PM Mike Bratcher, OCD December 23, 2015 1:10 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Flow line to the East of the lease road was struck by unknown object and cut causing a 2bbl spray in the lease road. The transfer pump was immediately isolated and a crew was contacted to fuse the line back together. Repairs have been made to the line.

Describe Area Affected and Cleanup Action Taken.*

2bbls of produced water was released from a flow line. The size of the affected area is 10'x10' contained completely on the lease road to the East of the Cotton Draw Unit 65. 0bbls were recovered and an environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: 12/24/15	Expiration Date: N/A
E-mail Address: Sheila.Fisher@dvn.com	Conditions of Approval:	
Date: 12/23/15 Phone: 575.748.1829	Remediation per O.C.D. Rules & Guidelines	
	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 12/24/15

2RP-3467

Patterson, Heather, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Wednesday, December 23, 2015 1:17 PM
To: Jim Amos (jamos@blm.gov); Shelly Tucker (stucker@blm.gov); Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Fulks, Brett; Scrogum, Sandy; Carter, Ray; Michael, Garry
Subject: Cotton Draw Unit 65_2bbls pw in lease road_12.22.15
Attachments: Cotton Draw Unit 65_2bbls pw in lease road_Initial C-141_12.22.15.doc; Cotton Draw Unit 65_2bbls pw in lease road_GIS Image_12.22.15.pdf; Cotton Draw Unit 65_2bbls pw in lease road_picture 1 of 1_12.22.15.jpg

Good Morning,

Attached please find the Initial C-141, GIS Image and photo for the 2bbls produced water release on the lease road East of the Cotton Draw Unit 65 on 12.22.15.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.