

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JAN 11 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1601227198

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: GRAVE DIGGER STATE COM #008H	Facility Type: Well

Surface Owner: Fee	Mineral Owner: State	API No. 30-015-43397
--------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	2	20S	25E	170'	South	1610'	West	Eddy

Latitude 32.5956523 Longitude -104.45835101

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 19 bbls PW	Volume Recovered: unknown
Source of Release: Frac Tank Valve	Date and Hour of Occurrence: 12/21/2015 12:00 am	Date and Hour of Discovery: 12/21/2015 6:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A leak from the frac tank valve was discovered on the backside of the tank.

Describe Area Affected and Cleanup Action Taken.*

The release ran off the backside of the location into the pasture. This release occurred on fee surface and was caused by a third party working on location. PIMA Tanks is taking responsibility for the clean-up. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amanda T. Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Signed By: <i>Mike [Signature]</i> Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 1/12/16	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 1/4/2015 Phone: 575-748-6940	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 2/12/16	

* Attach Additional Sheets If Necessary

2RP-3488

Bratcher, Mike, EMNRD

From: Amanda Trujillo Davis <ATrujillo@concho.com>
Sent: Monday, January 11, 2016 6:28 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Austin Weyant
Subject: (Notification/C-141) GRAVE DIGGER STATE COM #008H (30-015-43397)
Attachments: 12-21-2015 Grave Digger State Com #8H (WH) Initial.pdf

Mr. Bratcher,

COG Operating LLC is reporting a release on the GRAVE DIGGER STATE COM #008H (30-015-43397)
Unit N Section 2, Township 20S Range 25E
The release occurred at 12/21/2015 at 12:00 am
Released: 19 bbls PW
Recovered: unknown

A leak from the frac tank valve was discovered on the backside of the tank. The release ran off the backside of the location into the pasture. This release occurred on fee surface and was caused by a third party working on location. Pima Tanks is taking responsibility for the clean-up. Souder, Miller, & Associates will be handing the clean up on behalf of Pima Tanks Services and Concho. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo Davis
Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained