

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

FEB 02 2016

Form C-141
Revised August 8, 2011

RECEIVED
Submit to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1603629420 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC <u>229137</u>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: T H O STATE #001	Facility Type: Battery

Surface Owner: Fee	Mineral Owner: State	API No. 30-015-34515
--------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	34	17S	28E	2310	North	990	West	Eddy

Latitude Longitude

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 20 bbls Oil	Volume Recovered: 18 bbls Oil
Source of Release: Tank Over flow	Date and Hour of Occurrence: 1/5/2016 2:00 pm	Date and Hour of Discovery: 1/5/2016 2:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a tank overflowed during a storm that caused accessibility to be limited. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within the earthen containment. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Robert McNeill</u>	OIL CONSERVATION DIVISION	
Printed Name: Robert McNeill	Signed By: <u>[Signature]</u> Approved by Environmental Specialist:	
Title: Environmental Manager	Approval Date: <u>2/5/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: rmcneill@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: January 19, 2016 Phone: 432-230-0077	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 2/8/16

2RP-3530

Bratcher, Mike, EMNRD

From: Amanda Trujillo Davis <ATrujillo@concho.com>
Sent: Monday, February 01, 2016 4:27 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: (Notification/C-141) T H O State #1 (30-015-34515)
Attachments: 1-5-2016 T H O State #1 (TB) Initial.pdf

Mr. Bratcher,

COG Operating LLC is reporting a release on the T H O State #1 (30-015-34515)
Unit E Section 34, Township 17S Range 28E
The release occurred at 1/5/2016 at 2:00 pm
Released: 20 bbls Oil
Recovered: 18 bbls Oil

This release was caused by a tank overflow. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo Davis
Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.