

**RECEIVED**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

AUG 04 2010

Form C-141  
Revised October 10, 2003

HOBBSD  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action****OPERATOR**☒ Initial Report ☐ Final Report

Name of Company Cimarex Energy Co	Contact Mark Bishop	
Address 702 N Grimes	Telephone No. 575-602-1002	
Facility Name Cooper Federal #1	Facility Type Flowing gas well	
Surface Owner Woolworth Trust	Mineral Owner	Lease No.

**LOCATION OF RELEASE API #30-025-24561-00-00**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	21	24-S	36-E	1980'	NL	2180'	WL	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Oil spill	Volume of Release 5-10 bbl	Volume Recovered None
Source of Release water tank	Date and Hour of Occurrence 8-2-10 unknown what hour	Date and Hour of Discovery 8-3-10 11:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not required	If YES, To Whom? Larry Johnson	
By Whom? Mark Bishop	Date and Hour 8-3-10 4:30PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

WATER @ 125'

Describe Cause of Problem and Remedial Action Taken.\*

A water tank containing oil ran over but was contained by the dyke. Some of the oil leached through to the outside of the dyke. Safety & Environmental Solutions Inc. will be supervising the cleanup operation. The affected soil will be removed and clean soil will be brought in.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is inside and on the side of the tank battery containment

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Mark Bishop</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Mark Bishop	Approved by <i>ENV. ENGINEER: Jeffery Spring</i> District Supervisor	
Title: Production Foreman	Approval Date: 08/05/10	Expiration Date: 10/05/10
E-mail Address: mbishop@cimarex.com	Conditions of Approval: SUBMIT FINAL C-141 BY 10/05/10	Attached <input type="checkbox"/>
Date: 8-3-10 Phone: 575-602-1002	IRP-05-11-2713	

\* Attach Additional Sheets If Necessary