

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 17 2013

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company XTO Energy, Inc.	Contact Dudley McMinn
Address 200 N. Loraine, Suite 800, Midland, TX, 79701	Telephone No. 432-682-8873
Facility Name Southwest Royalties Inc	Facility Type Tank battery
Surface Owner Eidson Ranch	Mineral Owner State of New Mexico
API No. near 30-025-24661	

LOCATION OF RELEASE

Unit Letter E	Section 7	Township 17S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.852183 Longitude 103.501633

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 15 barrels	Volume Recovered 10 barrels
Source of Release 4" steel gathering line	Date and Hour of Occurrence	Date and Hour of Discovery 10/16/2012 @ 15:45
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Plane discovered 3 leaks on line to Southwest Royalties Battery - 4" steel gathering line. XTO personnel were notified, and the following actions were taken: 4" steel gathering line was shut-in and a flow-line clamp installed. Vacuum truck was dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.*

Approximate area affected 4,430 sq. ft. area of pasture/grassland. Following clean-up actions have taken:

1. Approximately 2,750 cubic yards of soil was excavated and hauled to OCD approved disposal (R360 - Halfway) and landfarm (JDann)
2. Highest TPH in confirmations samples from bottom and sidewalls was 348 mg/Kg with RRAL of 1,000 mg/Kg;
3. Highest chloride in sidewall confirmation sample was 189 mg/Kg;
4. Highest chloride in bottom confirmation sample was 43.6 mg/Kg;
5. Approval to fill excavations with clean approved by OCD on March 4, 2013 (Initial C-141 approval date);
6. Excavations were filled between March 14 - 19, 2013 with soil acquired from land-owner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dudley McMinn</i>	OIL CONSERVATION DIVISION	
Printed Name: Dudley McMinn	Approved by Environmental Specialist: <i>Dudley McMinn</i> Environmental Specialist	
Title: EHS Manager	Approval Date: 5/17/13	Expiration Date: -
E-mail Address: Dudley_McMinn@xtoenergy.com	Conditions of Approval: -	Attached <input type="checkbox"/>
Date: April 26, 2013 Phone: (432) 682-8873	IRP-83-13-2907	

* Attach Additional Sheets If Necessary