

AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pSAD1327750588

1RP - 2967

COG OPERATING LLC

District 1 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District IUI 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

HOBBS OCD

Form C-141 Revised October 10, 2003

OCT 0 4 2013
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

						OPERA'			al Report		Final Repo		
Name of Company COG OPERATING LLC						Contact Pat Ellis							
Address 600 West Illinois Avenue, Midland, TX 79701						Telephone No. 432-230-0077							
Facility Na	me PRO	HIBITION	FEDER	AL UNIT #002		Facility Typ	е	SWD					
Surface Owner Federal Mineral Owner						Lease No. (API#) 30-025-31716							
				LOCA	TION	OFRE	LEASE						
Unit Letter K							Feet from the	East/V	Vest Line	County	Lea		
				Latitude 32.4	0443	Longi	tude 103.64730)					
				NAT	URE	OF REL	THE RESERVE OF THE PARTY OF THE						
Type of Release Oil and produced water												7bbls of oil	
Source of Release Water tank						30bbls of produced water 25bbl Date and Hour of Occurrence Date and Hour of Dis						duced water	
Source of Refease, water tank											3 08:00am		
Was Immediate Notice Given?						If YES, To Whom?							
						Geoffrey Leking - NMOCD							
By Whom? Michelle Mullins						Date and Hour 09-25-2013 07:39							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
			Yes 🗵	No									
If a Waterco	urse was Impa	cted, Descri	be Fully.										
Danilla Ca	use of Problem	/ D	li-1 Ai	T-1 #									
Describe Ca	use of Problem	and Remet	nai Actio	n Taken.									
Plunger on t	riplex pump br	oke. Replac	ed the trip	olex pump.				DT	W=3	3550	DRL 10	14113	
Describe Ar	ea Affected an	d Cleanup A	ction Tak	en.*									
Initially 10h	ble of oil and 2	Obble of pro	duand w	iter were released	duator	madamiant	failure on the trim	las arms	m Causins	the meter	touls to o	wallen We	
				duced water with									
				neate any possible									
	prior to any si												
11 1	16 -1 -1 -1 -6				1-1-1-1	1 C		1 .	1.1		1000		
regulations	all operators ar	ormation gi	ven above	is true and comp id/or file certain r	elease n	ne best of my	knowledge and u	inderstai	ions for re	cases which	h may en	danger	
				e of a C-141 repo									
should their	operations hav	e failed to a	dequately	investigate and r	emediat	e contaminati	on that pose a thr	reat to gr	round wate	r, surface v	vater, hur	man health	
				stance of a C-141	report d	oes not reliev	e the operator of	responsi	ibility for o	compliance	with any	other	
federal, state	or local laws	and/or regu	lations.				OII CON	CEDI	ATION	DIVIG	IAON		
							OIL CON	DEKV	ATION	DIVIS	ON		
Signature:	IK	about .	Len	h			000	PKU	(lean	12	CM	No.	
			4	1		Approved by	District Supervis	or: W	74			0	
Printed Nam	ie:	Rober	t Grubbs .	Jr.			-	Envi	ronment	al Spec	lalist		
Title:	Se	nior Enviror	nmental C	oordinator		Approval Da	10104113		Expiration	Date: 2	04/13	5	
E-mail Add	ess:	rgrubbs@	concho.c	om		Conditions o	f Approval: SUR	MIT	FINAL				
						C-141 BY 12/04/13				Attached [
Date: 10-	03-2013		Phone:	432-661-660	1	C-141 1	21 1200	2		IRP-1	0-13-	2967	

