

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

FEB 23 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

**1981405638132** **198463**

Name of Company Oxy Permian Ltd.		Contact Casey Summers	
Address 6 Desta Drive, Midland, TX 79705		Telephone No. (575) 513-8289	
Facility Name Government AB Federal #13		Facility Type Well	
Surface Owner BLM	Mineral Owner	API No. 30-015-40920	

### OPERATOR

☒ Initial Report ☐ Final Report

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	10	20S	28E					Eddy County, NM

Latitude N 32.58979° Longitude W 104.15874°

### NATURE OF RELEASE

Type of Release Oil and Produced water	Volume of Release 0.5 bbl oil, 15 bbls produced water	Volume Recovered 2 bbls produced water, skim oil
Source of Release Livestock opened valve at the well head	Date and Hour of Occurrence 02/11/2016	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM	
By Whom? Kathy Purvis @ BBC International Inc.	Date and Hour 02/12/2016 @ 3:16 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Livestock opened a valve at the well head spilling 0.5 bbl oil and 15 bbls of produced water. A vacuum truck recovered 2 bbls of produced water and skim oil and the valve was closed.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 105' x 57' on location around the well head. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Casey Summers		Signed By:  Approved by Environmental Specialist:	
Title: NM Environmental Advisor		Approval Date: 2/25/16	Expiration Date: N/A
E-mail Address: Casey.Summers@oxy.com		Conditions of Approval:	
Date: 2-23-16 Phone: (575) 513-8289		Attached <input type="checkbox"/>	

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 3/24/16

2RP-3562

\* Attach Additional Sheets If Necessary

## Bratcher, Mike, EMNRD

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Tuesday, February 23, 2016 11:23 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov  
**Cc:** Casey\_Summers@oxy.com; dusty\_wilson@oxy.com; Jennifer\_duarte@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial C-141, Government AB Federal #13  
**Attachments:** Initial C-141, Government AB Federal #13.pdf

Attached is the initial C-141 for a leak that occurred at the Government AB Federal #13 on 02/11/2016 in Eddy County, NM. Receipt notification via email is greatly appreciated.

*Kathy Purvis*

BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

**Patterson, Heather, EMNRD**

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Friday, February 12, 2016 3:16 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov  
**Cc:** Casey\_Summers@oxy.com; dusty\_wilson@oxy.com; Jennifer\_duarte@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com; kathy@bbcinternational.com  
**Subject:** Government AB Federal #13

This is to inform you that Oxy Permian had a leak at the Government AB Federal #13 on February 11, 2016. Oxy spilled 0.5 bbl of oil and 15 bbls of produced water due to livestock opening valve at the well head. The preliminary report shows the leak measuring approximately 18' x 7' on location. Recovery is in progress. The release is located in U/L H of Section 10, T20S, R28E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: From Artesia, take HWY 82 to NM206, turn right and go to Angel Ranch Rd, turn right and go to Burton Flat Battery, turn left at battery, turn left across from the Government Y battery, turn right at the Government AB 2 Battery, Well is on right side of road. API# 30-015-40920 GPS coordinates: N 32.58981° W 104.15870°

**Kathy Purvis**

BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)