

District I - (505) 393-6161  
P.O. Box 1980  
Hobbs, NM 88241-1980  
District II - (505) 748-1283  
811 South First  
Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Road  
Aztec, NM 87410  
District IV - (505) 827-7131

State of New Mexico  
Energy Minerals and Natural Resources Department  
Oil Conservation Division  
2040 South Pacheco Street  
Santa Fe, New Mexico 87505  
(505) 827-7131

Form C-141  
Originated 2/13/97

Submit 2 copies to  
Appropriate District  
Office in accordance  
with Rule 116 on  
back side of form

30-015-27162  
nmlb0435049343

## Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name <b>POGO Producing Co.</b>	Contact <b>Pat Ellis</b>
Address <b>P.O. Box 10340 Midland TX</b>	Telephone No. <b>432-685-8148</b>
Facility Name <b>AMAX 24-8 Tank Battery</b>	Facility Type <b>TANK BATTERY</b>
Surface Owner <b>BIM</b>	Mineral Owner <b>BIM</b>
	Lease No. <b>NM 40655</b>

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<b>24</b>	<b>23 S</b>	<b>31 E</b>	<b>2160'</b>	<b>FSL</b>	<b>330'</b>	<b>FWL</b>	<b>EDDY</b>

## NATURE OF RELEASE

Type of Release <b>salt water</b>	Volume of Release <b>250 BBls</b>	Volume Recovered <b>240 BBls</b>
Source of Release <b>Water Pump</b>	Date and Hour of Occurrence <b>12/13/04</b>	Date and Hour of Discovery <b>8:30 am 12/13/04</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>ARTESIA OGD Linda Nelson</b>	
By Whom? <b>Clay Osborn</b>	Date and Hour <b>10:30 AM</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully (Attach Additional Sheets If Necessary)


Describe Cause of Problem and Remedial Action Taken (Attach Additional Sheets If Necessary)

**TRANSFER Pump. Picked up 240 BBls out of FIRE WALL. 1" Plug came out of water**

Describe Area Affected and Cleanup Action Taken (Attach Additional Sheets If Necessary)

**INSIDE FIRE WALL. HAD 6-8 BBls Run across Location. Picked up water with Pump Truck. Soil will Be Tested and Impacted Soil Removed.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: <b>CLAY OSBORN</b>	Approved by District Supervisor:		
Title: <b>Field Foreman</b>	Approval Date:	Expiration Date:	
Date: <b>12/13/04</b>	Phone: <b>432-631-0129</b>	Conditions of Approval:	Attached <input type="checkbox"/>

F  
F  
REM plan accepted