



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number:** pKJ1607052559

**1RP - 4211**

**PALADIN ENERGY CORP**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

Form C-141  
Revised August 1, 2011

SEP 04 2012  
2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Paladin Energy Corp.	Contact	Michael Horn
Address	4006 Dunkirk, Midland, TX, 79707	Telephone No.	432-634-6599
Facility Name	State C #003	Facility Type	Salt Water Disposal
Surface Owner	James Reed McCrory	Mineral Owner	Unknown
		Lease No.	30-025-34239

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	36	13S	37E	1550	FNL	10	FWL	Lea

Latitude 33° 9' 4.019" Longitude 103° 9' 44.791"

NATURE OF RELEASE

Type of Release	Produced water and crude oil	Volume of Release	30 water/5 oil	Volume Recovered	5 bbs
Source of Release	Tank struck by lightning	Date and Hour of Occurrence		Date and Hour of Discovery	8/25/12 6pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Tank was struck by lightning, ruptured, and released fluids. Standing fluids were recovered and saturated soils were scraped and stockpiled on site.

Describe Area Affected and Cleanup Action Taken.\*

The leak impacted the well pad and pasture area to the west. The site will be remediated to NMOCD standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contain or the environment. In addition, NMOCD acceptance of a C-141 report does not federal, state, or local laws and/or regulations.

APPROVED

Signature: <i>Michael Horn</i>	Approval		
Printed Name: <i>Michael Horn</i>			
Title: Operations Manager	Approval Date: 03/10/16	Expiration Date: 05/10/16	
E-mail Address: paladinmid@suddenlink.net	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 8/29/2012 Phone: 432-634-6599		RP 4211	

\* Attach Additional Sheets If Necessary

9/4



# Initial Field Data

## Surface Samples

Sample Description	CI-	PID
pt.3	2690	0.3
pt.4	2729	0.3


HOBBS OCD

SEP 04 2012

RECEIVED

## Samples on Pad

Sample Description	CI-	PID
northeast bottom	5269	0.3
northwest bottom	637	0.2
southeast bottom	607	0.2
southwest bottom	5289	0
middle bottom	1330	0
5pt. Bottom comp	3531	0.3



## PALADIN STATE C #3 AD

UL/ H SECTION 35  
UL/D & E SECTION 36  
T-13-S R-37-E  
LEA COUNTY, NM

0 25 50  
Feet

GPS date: 8/28/12 JK  
Drawing date: 8/29/12  
Drafted by: T. Grieco, L. Weinheimer

