JUN 1 8 2013
NMOCD ARTESIA

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

\	1	R	Release	e Notification	n a	nd Correc	tive Actio	n		
nTMh	131	10392	•	OPERAT			<u> </u>		Report	Final Report
Name of Company: Chevron 4323 Contact: Bradley Blevins										
Address: 1616 West Bender						Telephone No.: (575) 391-1462 ext. 86424				
Facility Name: Baish Federal Tank Battery Facility Type: Tank Battery										
Surface O	wner: Fo	ederal					a.: LC029389A			
LOCATION OF RELEASE BAISH Fed 2 30-015-25728										
Unit Letter B	Section 9	Township 18S	Range 31E	Feet from the	No	rth/South Line	Feet from the	E	ast/West Line	County Eddy
Latitude: N 32° 46' 2.0" Longitude: W 103° 52' 18.4"										
32.167222 NATURE OF RELEASE 103. 871778										
Type of Release: Produced water							lame of Release: ~160 bbls Volume Recovered: ~110 bbls			
Source of Release: Tank Battery							Date and Hour of Occurrence: Date and Hour of Discovery: May 9, 2013 A.M. May 9, 2013 A.M.			
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Mike Bratcher, NMOCD				
By Whom? Bradley Blevins						Date and Hour: May 10, 2013 @ 1430 hrs				
Was a Watercourse Reached? ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse: Not Applicable				
Describe Cause of Problem and Remedial Action Taken.* The release of approximately 160 barrels of produced water was the result of a lightning strike on a water tank; all fluid remained inside the firewall. A vacuum truck was utilized to recover any free liquids. An Emergency Response Team arrived at the release area and began continuous abatement of the impacted area. Describe Area Affected and Cleanup Action Taken.* Approximately 10,800 square feet of surface area within the confines of the berm was impacted by the release. Approximately 110 barrels of produced water was recovered from the site. Visibly stained soil was excavated and hauled away for disposal at a state approved facility. Soil samples were collected and submitted to Cardinal Laboratories for testing. Upon receiving acceptable results and NMOCD approval, the affected area will be backfilled, and returned to proper conditions. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.										
Signature: C			Approved by District Supervisor:							
Printed Name		<u> </u>	Approval Date: 19 2013 Expiration Date:							
E-mail Addre	4.13	Phone: (5	75) 391-1	462 ext. 86424			n per OCD R		8	Attached 🗆
Attach Additional Sheets If Necessary Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 2RP-1687										