District 1 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

۰.

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

APR 06 2016 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

State of New Mexico

Energy Minerals and Natural Resources

RECEIVED

<u> </u>	60983	35.241		ease Notific		OPERA		_	🖞 Initia	l Report	🔲 Final	Ren
Name of C	ompany	. <i>Oa 7 1</i> RKI E&P, L	LC	2410289		Contact	Taylor Jones	K		пкероп		Кер
Address				C, OK 73102		Telephone No. 539-573-7558						
Facility Na		er Federal 1	Facility Type : Oil and Gas Well									
								·				
Surface Owner: Federal Mineral Owner:						Federal			API No. 30-015-25744			
				LOCA	TION	N OF REI	LEASE					
Unit Letter	Section	Township	Range	Feet from the	North/S	South Line	Feet from the	East/We	st Line	County		
)	24	265	30E	460	FSL		1880	FEL		Eddy		
			-	Latitude: 32.	.02174	Longitude:	-103.8318447					
				NAT	URE	OF RELI						
Type of Rele						Volume of Release: 195 Bbls			Volume Recovered: 146 Bbls			
source of Re	elease Oil	Line between (oil tanks							and Hour of Discovery /16 – 0900hrs MT		
Was Immedi	iate Notice (Given?					Whom? Heather	Patterson			19 141 1	
Yes No Not Required									Afm	Ì		
By Whom? Taylor Jones						Date and H	lour: 04/06/16 - 1	:00 PM	F ·			
Was a Watercourse Reached?						1 '	olume Impacting t	he Waterc	course.			
🗌 Yes 🖾 No						N/A						
		em and Reme e two oil tanks		* N/A n Taken.* on ruptured, causi	ng the re	elease of crud	le oil.					
Oil load line Describe Are	between th	e two oil tanks and Cleanup /	s on locati Action Tal	n Taken.* on ruptured, causi <en.*< td=""><td>-</td><td></td><td></td><td>n but stay</td><td>ed on loc</td><td>ation Reco</td><td>overed standing</td><td></td></en.*<>	-			n but stay	ed on loc	ation Reco	overed standing	
Oil load line Describe Ard Spill was co	between th ea Affected ntained to ea	e two oil tanks and Cleanup / arthen (unlined	s on location Action Tal d) berm, w	n Taken.* on ruptured, causi	.5 bbls o	of oil which v	went through bern	n, but stay	ed on loc	ation. Reco	overed standing	, fluic
Oil load line Describe Art Spill was co- by vacuum t I hereby cert regulations a public health should their or the enviro	between th ea Affected ntained to e ruck, recove lify that the all operators to or the envi operations I onment. In a	e two oil tanks and Cleanup / arthen (unline- cred 146 bbls of information gi are required t ironment. The have failed to a	s on location Action Tal d) berm, w of oil. All iven above o report an e acceptant adequately OCD accept	n Taken.* on ruptured, causi cen.* vith exception of 0	0.5 bbls of e remove lete to the clease no ort by the emediate	of oil which we and taken the best of my otifications are NMOCD me contaminati	went through bern to disposal. knowledge and u nd perform correc arked as "Final R ion that pose a thr re the operator of	nderstand tive action eport" doe eat to grou responsibi	that purs ns for release not reliand water lity for c	uant to NN cases which eve the op to surface we compliance	AOCD rules and h may endanged erator of liabili vater, human he with any other	d r ty
Oil load line Describe Ard Spill was couby vacuum t I hereby cert regulations a public health should their or the enviro	between th ea Affected ntained to e ruck, recove lify that the all operators to or the envi operations I onment. In a	e two oil tanks and Cleanup / arthen (unline- cred 146 bbls of information gi are required t ironment. The have failed to a addition, NMC	s on location Action Tal d) berm, w of oil. All iven above o report an e acceptant adequately OCD accept	n Taken.* on ruptured, causi cen.* vith exception of 0 affected soil to be e is true and comp nd/or file certain re ce of a C-141 repo	0.5 bbls of e remove lete to the clease no ort by the emediate	of oil which we and taken the best of my otifications are NMOCD me contaminati	went through bern to disposal. knowledge and u nd perform correc arked as "Final R ion that pose a thr	nderstand tive action eport" doe eat to grou responsibi	that purs ns for release not reliand water lity for c	uant to NN cases which eve the op to surface we compliance	AOCD rules and h may endanged erator of liabili vater, human he with any other	d r ty
Oil load line Describe Art Spill was co- by vacuum t I hereby cert regulations a public health should their or the enviro	between th ea Affected ntained to e ruck, recove lify that the all operators to or the envi operations I onment. In a	e two oil tanks and Cleanup / arthen (unline- cred 146 bbls of information gi are required t ironment. The have failed to a addition, NMC	s on location Action Tal d) berm, w of oil. All iven above o report an e acceptant adequately OCD accept	n Taken.* on ruptured, causi cen.* vith exception of 0 affected soil to be e is true and comp nd/or file certain re ce of a C-141 repo	0.5 bbls of e remove lete to the clease no ort by the emediate	of oil which we and taken the best of my otifications are NMOCD me contaminati	went through bern to disposal. knowledge and u nd perform correc arked as "Final R ion that pose a thr re the operator of	nderstand tive action eport" doe eat to grou responsibi	that purs ns for release not reliand water lity for c	uant to NN cases which eve the op to surface we compliance	AOCD rules and h may endanged erator of liabili vater, human he with any other	d r ty
Oil load line Describe Art Spill was con by vacuum t I hereby cert regulations a public health should their or the enviro federal, state	between th ea Affected ntained to e ruck, recove lify that the all operators or the envi operations I onment. In a e, or local la	e two oil tanks and Cleanup / arthen (unline- cred 146 bbls of information gi are required t ironment. The have failed to a addition, NMC ws and/or regi	s on location Action Tal d) berm, w of oil. All iven above o report an e acceptant adequately OCD accept	n Taken.* on ruptured, causi cen.* vith exception of 0 affected soil to be e is true and comp nd/or file certain re ce of a C-141 repo	9.5 bbls of e remove lete to the elease no ort by the emediate report do	of oil which v ed and taken i ne best of my otifications are NMOCD m contaminationes not reliev	went through bern to disposal. knowledge and u nd perform correc arked as "Final R ion that pose a thr re the operator of	nderstand etive action eport" doe eat to grou responsibi SERVA	that purs ns for release not reliand water lity for control of the second ATION	uant to NN cases which eve the op to surface we compliance	AOCD rules and h may endanged erator of liabili vater, human he with any other	d r ty
Oil load line Describe Art Spill was con by vacuum t I hereby cert regulations a public health should their or the enviro federal, state Signature: Printed Nam	between th ea Affected ntained to e ruck, recove lify that the all operators or the envi operations I onment. In a e, or local la	e two oil tanks and Cleanup / arthen (unline ered 146 bbls of information gi are required t ironment. The have failed to a addition, NMC ws and/or regu	s on location Action Tal d) berm, w of oil. All iven above o report an e acceptant adequately OCD accept	n Taken.* on ruptured, causi cen.* vith exception of 0 affected soil to be e is true and comp nd/or file certain re ce of a C-141 repo	9.5 bbls of e remove lete to the clease no ort by the emediate report do	of oil which v ed and taken i ne best of my otifications are NMOCD m contaminationes not reliev	went through bern to disposal. knowledge and u nd perform correc arked as "Final R ton that pose a thr te the operator of <u>OIL CON</u> Environmental S	nderstand etive action eport" doe eat to grou responsibi SERVA pecialist:	that purs ns for release not reliand water lity for control of the second ATION	uant to NM cases which eve the op surface w ompliance DIVISI	AOCD rules and h may endanged erator of liabili vater, human he with any other	d r ty
Dil load line Describe Art Spill was co- by vacuum t I hereby cert regulations a bublic health should their or the enviro federal, state Signature: Printed Nam Fitle: Safety	between th ea Affected ntained to e ruck, recove lify that the all operators or the envi operations I onment. In a e, or local la <u>current</u> e: Taylor J y Specialist	e two oil tanks and Cleanup / arthen (unline ered 146 bbls of information gi are required t ironment. The have failed to a addition, NMC ws and/or regu	s on location Action Tab d) berm, w of oil. All iven above o report an e acceptance adequately OCD acceptance alations.	n Taken.* on ruptured, causi cen.* with exception of 0 affected soil to be e is true and comp nd/or file certain ru ce of a C-141 repo v investigate and ro otance of a C-141 r	2.5 bbls of e remove lete to the clease no ort by the emediate report do	of oil which v ed and taken to be best of my otifications are NMOCD m contaminations not reliev Approved by Approval Date Conditions of	went through bern to disposal. knowledge and u nd perform correc arked as "Final R on that pose a thr e the operator of <u>OIL CON</u> Environmental S te: <u>411116</u>	nderstand etive action eport" doe eat to grou responsibi SERVA pecialist: « Ex	that purs ns for releas not reliand water lity for c TION	Date:	MOCD rules and h may endanged erator of liabili vater, human he with any other ON	d r ty
Oil load line Describe Art Spill was con by vacuum t I hereby cert regulations a public health should their or the enviro federal, state Signature: Printed Nam Title: Safety	between th ea Affected ntained to e ruck, recove lify that the all operators or the envi operations I operations I operations I operations I e, or local la <u>e</u> : Taylor J y Specialist ress: Taylor	e two oil tanks and Cleanup / arthen (unline- cred 146 bbls of information gi are required t ironment. The have failed to a addition, NMC ws and/or regu addition, NMC us and/or regu	s on location Action Tab d) berm, wo of oil. All iven above o report an eacceptane adequately OCD acceptane adequately OCD acceptane add Acceptane add Acceptane add Acceptane add add Acceptane add Acceptane add Acceptane add Acceptane add Acceptane add Acceptane add Acceptane add Acceptane add Acceptane add Acceptane add Acceptane add Acceptane Acceptane add Acceptane Acceptane add Acceptane Accept	n Taken.* on ruptured, causi cen.* with exception of 0 affected soil to be e is true and comp nd/or file certain ru ce of a C-141 repo v investigate and ro otance of a C-141 r	2.5 bbls of e remove lete to the clease no ort by the emediate report do	of oil which v ed and taken i ne best of my otifications are NMOCD m e contaminati bes not reliev Approved by Approval Dat Conditions of Remedia	went through bern to disposal. knowledge and u nd perform correc arked as "Final R ton that pose a thr te the operator of <u>OIL CON</u> Environmental S te: 41110	nderstand etive action eport" doe eat to grou responsibi SERVA pecialist: • Ex D. Rule	that purs ns for release not reliand water lity for control ATION ATION spiration	Date:	MOCD rules and h may endanged erator of liabili vater, human he with any other ON	d r ty

Patterson, Heather, EMNRD

From:	Jones, Taylor <taylor.jones@wpxenergy.com></taylor.jones@wpxenergy.com>
Sent:	Wednesday, April 06, 2016 1:44 PM
То:	Patterson, Heather, EMNRD; stucker@blm.gov
Subject:	WPX Energy (RKI E&P) Spill notification
Attachments:	NM_GingerFed1_InitialC141(040616)-signed.pdf

Heather/Shelly

Please see attached OCD form C-141 for a spill occurring at the RKI (Now WPX Energy) operated Ginger Federal 1, API: 30-015-25744

Please let me know if you have any questions.

Regards,

Taylor Jones Safety Specialist II **WPX Energy, Inc.** 210 Park Avenue, Suite 700 Oklahoma City, OK 73102 **539-573-7558** (o) | 405.326.0791 (m) <u>NEW: taylor.jones@wpxenergy.com</u>