

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: Plains Marketing, LP	Contact: Camille Bryant	
Address: 2530 State Hwy. 214, Denver City, TX 79323	Telephone No. (575)441-1099	
Facility Name: BOPCO Station	Facility Type: Pump	
Surface Owner: BLM	Mineral Owner:	Lease No.

LOCATION OF RELEASE

Unit Letter P	Section 21	Township 24S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.197262° North Longitude 103.777821° West

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 14 bbls	Volume Recovered 10 bbls
Source of Release Pump	Date and Hour of Occurrence 04/02/2014 @ 08:00	Date and Hour of Discovery 04/02/2014 @ 08:40
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Verbal notification to Mike Bratcher (voicemail)	
By Whom? Camille Bryant	Date and Hour 04/02/2014 @ 14:30	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Gasket failure on a pump liner cover resulted in a release of crude oil. The gasket on the pump was replaced.		
Describe Area Affected and Cleanup Action Taken.* The released crude oil impacted an area measuring approximately 148' x 60' inside the facility. The impacted area was remediated per NMOCD recommended guidelines. Soil samples collected from the floor and sidewalls of the excavation were analyzed by an NMOCD-approved laboratory, and concentrations of benzene, BTEX, TPH, and chloride were below the recommended remediation action levels established for the site by the NMOCD. Please reference the attached <i>Remediation Summary & Site Closure Request</i> for complete remediation details.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Camille Bryant	Approved by Environmental Specialist:	
Title: Remediation Coordinator	Approval Date:	Expiration Date:
E-mail Address: cjbrant@paalp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/12/14 Phone: (575)441-1099		

* Attach Additional Sheets If Necessary

NM OIL CONSERVATION
ARTESIA DISTRICT

JAN 06 2015

RECEIVED