## NM OIL CONSERVATION

ARTESIA DISTRICT

MAY 1 7 2016

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in RECEIVED dance with 19.15.29 NMAC.

State of New Mexico **Energy Minerals and Natural Resources** 

District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210

Oil Conservation Division 1220 South St. Francis Dr.

1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505													
Release Notification and Corrective Action													
NAB161443382D						OPERATOR			☐ Initial Report ☐ Final Report				
Name of Company OXY USA WTP LP						Contact Jennifer Duarte							
Address PC		Telephone No. 713-513-6640											
Facility Name STATE CV COM #1 Facility Type WELL													
Surface Owner Mineral Owner							API No. 30-015-21927						
		, <u>.</u>				N OF RE							
Unit Letter E	Section 16	Township 20S	Range 28E	Feet from the 1980	North NORT			East/W WEST	est Line	County EDDY			
LatitudeLongitude													
NATURE OF RELEASE													
Type of Rele			Volume of Release 300 MCF			Volume Recovered 0							
Source of Release GAS – FLARE						Date and Hour of Occurrence 04/08/2016 – BEGAN 04/20/2016 - ENDED			Date and Hour of Discovery				
Was Immediate Notice Given?  Yes No Not Required  If YES, To Whom?													
By Whom? Was a Water	course Denc	had?				Date and Hour  If YES, Volume Impacting the Watercourse.							
Wits il Water	Course Read		Yes [	] No		7 LLS, Volume impacting the watercourse.							
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.*													
Flaring is due to DCP high line pressure and restarting gas lift compressor.													
Describe Area Affected and Cleanup Action Taken.*													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature: prings lead							OIL CONSERVATION DIVISION  Signed By Mile Learning  Approved by Environmental Specialist:						
Printed Name Title: ENVI				Approval Date: 5/30/16 Expiration Date: N/A									
E-mail Address: jennifer_duarte@oxy.com						Conditions of Approval:							
D	6 2016		D.	212 512 6612			Γ.	111/1	<u></u>	1	_	1	

\* Attach Additional Sheets If Necessary

Phone: 713-513-6640

5-16-2016

## Bratcher, Mike, EMNRD

From:

Jennifer\_Duarte@oxy.com

Sent:

Tuesday, May 17, 2016 4:07 PM

To:

Bratcher, Mike, EMNRD

Subject:

State CV Com CTB

**Attachments:** 

Scanned from a Xerox Multifunction Device001.pdf; Scanned from a Xerox Multifunction

Device002.pdf.

Please see the attached C141s for flares. One is a final Flare and the other is an initial flare report.

Thank you,

Jennifer Duarte

**Environmental Specialist** 

713-513-6640