


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

FAB1614452120  
NAB1614452503

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Plains Pipeline, LP	Contact	Jason Henry
Address	2530 Hwy 214 - Denver City, Tx 79323	Telephone No.	(575) 441-1099
Facility Name	Loco Hills Station Bypass Line	Facility Type	Pipeline

Surface Owner	BLM	Mineral Owner		Lease No.	
---------------	-----	---------------	--	-----------	--

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	23	17S	31E					Eddy

32.829166 103.837006  
Latitude N 32° 49' 23.4" Longitude W 103° 50' 15.6"

#### NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	35 bbls	Volume Recovered	25 bbls
Source of Release	4" Steel Bypass Line	Date and Hour of Occurrence	11/19/2009	Date and Hour of Discovery	11/19/2009 11:00
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Verbal notification to Mike Bratcher on 11/20/2009		
By Whom?	Jason Henry	Date and Hour	11/20/2009 @ 10:30		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Internal corrosion of a 4-inch bypass line resulted in a release of crude oil, the free product was recovered with a vacuum truck, and the impacted soil has been excavated and stockpiled.

Describe Area Affected and Cleanup Action Taken.\*

The released crude resulted in a surface stain that measured approximately 40' x 30'. The impacted area will be remediated per applicable BLM/NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jason Henry</i>	OIL CONSERVATION DIVISION	
Printed Name: Jason Henry	Approved by District Supervisor: <i>[Signature]</i>	
Title: Remediation Coordinator	Approval Date: 5/20/10	Expiration Date: _____
E-mail Address: jhenry@paalp.com	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date: 12/09/2009	Phone: (575) 441-1099	

\* Attach Additional Sheets If Necessary

222 3710