

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 13 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1616628121		OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Name of Company Cimarex Energy 1103 1083		Contact Christine Alderman	
Address 600 N Marienfeld Ste 600 Midland TX		Telephone No. 432-853-7059	
Facility Name Marquardt Fed 15H		Facility Type Production	

Surface Owner BLM	Mineral Owner	API No. 30-015-42471
-------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	01	25S	26E	200	S	1550	W	Eddy

Latitude 32.15232 Longitude -104.249931

NATURE OF RELEASE

Type of Release crude oil	Volume of Release 15 bbls	Volume Recovered 14 bbls
Source of Release truck	Date and Hour of Occurrence 06/11/2016	Date and Hour of Discovery 06/11/2016
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson/Shelly Tucker	
By Whom? Christine Alderman	Date and Hour 06/13/2016 3:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NA

Describe Cause of Problem and Remedial Action Taken.*

While loading oil at aq LACT unit, the driver of the truck overfilled his tank.

Describe Area Affected and Cleanup Action Taken.*

All fluids stayed on location and the trucking company hydrovac-ed impacted area. Tetra Tech is going to go out and get confirmation samples and a closure report will be submitted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Christine Alderman	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist: [Signature]	
Title: ESH Supervisor	Approval Date: 6/14/16	Expiration Date: N/A
E-mail Address: calderman@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/13/2016 Phone: 432-853-7059	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 7/14/16

2RD-3733

Patterson, Heather, EMNRD

From: Christine Alderman <calderman@cimarex.com>
Sent: Monday, June 13, 2016 2:14 PM
To: Patterson, Heather, EMNRD; stucker@blm.gov; Amos, James A (jamos@blm.gov)
Cc: Gloria Garza
Subject: Marquart Fed 15H (30-015-42471)
Attachments: 20160613150529620.pdf

All,

We had a reportable spill at the above named location 6/11/2016. An oil hauler was filling his truck at the LACT unit, and overfilled. Approximately 15 bbls of crude was released and approximately 14 bbls were recovered.

The hauling company was out there this weekend with a hydro-vac and removed the impacted soils. I have contracted TetraTech to grab samples to confirm we have gotten all the hydrocarbon impact.

Please see attached C-141. Thank you!

Christine Alderman

Cimarex Energy Co.



ESH Supervisor – Permian Basin
Midland TX
Cell – 432.853.7059