

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION  
ARTESIA DISTRICT

JUN 10 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1616633332 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Cimarex Energy	Contact Christine Alderman
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059
Facility Name Wigeon 23 Fed Com 1	Facility Type Production
Surface Owner BLM	Mineral Owner
API No. 30-015-33563	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	23	25S	26E	1650	S	1650	E	Eddy

Latitude 32.11264 Longitude -104.26011

NATURE OF RELEASE

Type of Release produced water	Volume of Release 15 bbls	Volume Recovered 8 bbls
Source of Release 2" steel dump line	Date and Hour of Occurrence 06/09/2016	Date and Hour of Discovery 06/09/2016
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Shelly Tucker	
By Whom? Christine Alderman	Date and Hour 6/10/2016 11:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* The 2" steel water dump line developed a leak due to corrosion. A vacuum truck recovered 8 bbls of produced water.		
Describe Area Affected and Cleanup Action Taken.* All fluids stayed on the location pad. An environmental company will be contracted to delineate and submit work plan to remediate.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Christine Alderman	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist: [Signature]	
Title: ESH Supervisor	Approval Date: 6/14/16	Expiration Date: N/A
E-mail Address: calderman@cimarex.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 6/10/2016 Phone: 432-853-7059	SUBMIT REMEDIATION PROPOSAL NO	

\* Attach Additional Sheets If Necessary

LATER THAN: 7/14/16

2RP-3735

**Patterson, Heather, EMNRD**

---

**From:** Christine Alderman <calderman@cimarex.com>  
**Sent:** Friday, June 10, 2016 9:52 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov; Amos, James A (jamos@blm.gov)  
**Cc:** Gloria Garza  
**Subject:** Wigeon 23 Fed Com 1 (30-015-33563)  
**Attachments:** 20160610104648064.pdf

All,

On June 9, 2016 a release occurred at the above named lease in Eddy County. A 2" steel water dump line was corroded and caused 15 bbls of produced water to be released, and 8 bbls were recovered.

This line is being replaced. An environmental company will be contracted to delineate and submit work plan for approval.

Please let me know if you have any questions. Thank you. C-141 is attached.

Christine Alderman

Cimarex Energy Co.



ESH Supervisor – Permian Basin  
Midland TX  
Cell – 432.853.7059