

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

JUN 10 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB16161633908		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Yates Petroleum Corporation		Contact Amber Griffin		
Address 105 S. 4 th Street Artesia, NM 88210		Telephone No. 575-748-1471		
Facility Name Satchmo SWD State #1		Facility Type Well/Tanks		
Surface Owner State	Mineral Owner State	API No. 30-015-42492		

LOCATION OF RELEASE

Unit Letter B	Section 36	Township 25S	Range 31E	Feet from the 330	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.09297 Longitude 103.72897

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 15 B/PW	Volume Recovered 10 B/PW
Source of Release 8" poly line	Date and Hour of Occurrence 6/3/2016; PM	Date and Hour of Discovery 6/3/2016; PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N/A



Describe Cause of Problem and Remedial Action Taken.*

An 8" poly line from the H pump to the booster pump ruptured. Valves upstream and downstream were closed, the water pump was turned off and the water line was isolated.

Describe Area Affected and Cleanup Action Taken.

The affected area was inside the lined/bermed battery, along parts of the east and south side of the location and an 18' x 10' area off of the production pad. The release area was scraped and soils were hauled to a NMOCDD approved facility. Vertical and horizontal delineation samples will be taken from the release area and analysis will be run for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. Depth to Ground Water: >100' (approximately 300', per Chevron/Texaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCDD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCDD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCDD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amber Griffin	Approved by Environmental Specialist: 	
Title: Environmental Representative	Approval Date: 6/14/16	Expiration Date: N/A
E-mail Address: agriffin@yatespetroleum.com	Conditions of Approval:	
Date: June 10, 2016	Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Phone: 575-748-4111	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 7/14/16

2RD-3736

Patterson, Heather, EMNRD

From: Amber Griffin <AGriffin@yatespetroleum.com>
Sent: Friday, June 10, 2016 2:27 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amber Groves
Cc: Bob Asher; Chase Settle; Katie Parker; Veronica Alvarado
Subject: Satchmo SWD State #1 Initial C-141
Attachments: SatchmoSWDState1_C141_060316 Initial.pdf

Please find attached an Initial C-141 for a minor release that occurred at the Satchmo SWD State #1 on 6/3/2016.

Thank you,

Amber Griffin

Environmental Representative
Yates Petroleum Corporation
Office: (575) 748-4111
Cell: (575) 513-8799

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
